

ASS. REC. BY: kel

CS/EQI21008859/Gtf3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

5 ~~+~~

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKV2864

Yr Regn:

09 Sep 2015

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Qashqai c.c 1197

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

58473

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SINFEAJU14146288/

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/60R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Line Lamp

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24-08-21

Survey held at

w/s

12:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed COR \$4600 @ 5 days

RED: 6785.80;59%

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Other:

# 凱樑汽車服務

KAI LIANG MOTOR SERVICE

AUTOBAY @ KAKI BUKIT

BLK 1 KAKI BUKIT AVE 6 #01-101 SINGAPORE 417883

TEL: 67474189 FAX: 67431164

Email: kailiangmotor@kailiangmotor.com

**EQ Insurance Company Limited**

5 Maxwell Road, #17-00

Tower Block, MND Complex,

Singapore 069110

Our Ref: **SKV2962P**

Your Ref: **GBJ8780C** / Third party claim

**KK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

23-08-2021

Acknowledged by Repairer

Signature:

Date:

Road Traffic Accident involving **SKV2962P** and **GBJ8780C** on **20/08/2021**.

**Third party claim against GBJ8780C**

**SKV2962P Repairing Quotation**

|                      | Parts Description   | Amount<br>SGD(\$) |             |
|----------------------|---|-------------------|-------------|
| 2 pcs                | Nett Items:   |                   |             |
|                      | Rear boot door / <i>Quc</i>                                 | \$3368.90         | 2936.8      |
|                      | Rear bumper / <i>TN</i>                                     | \$796.70          | 717         |
|                      | Bumper side bracket X <i>NN</i>                             | \$48.90           | X           |
|                      | Bumper reinforcement X <i>Repair</i>                        | \$691.50          | X           |
|                      | Reverse sensor / <i>PM</i>                                  | \$480.00          | 200 (SN)    |
|                      | Rear windscreen glass and windscreen moulding ✓ <i>SCR</i>  | \$1306.80         | 930         |
|                      | Rear boot lower end penal (inner and outer) X <i>Repair</i> | \$482.60          | X           |
|                      | Rear door inner lock and lock motor X <i>NN</i>             | \$190.50          | X           |
|                      | Reverse camera X  | \$350.00          | X           |
|                      | Number plate lamp garnish / <i>Re.</i>                      | \$249.30          | ✓           |
|                      | Rear lamp @ \$295.30 each X <i>NN</i>                       | \$590.60          | X           |
|                      | Rear runner strip X   | \$230.00          | X           |
|                      | Rear windscreen gum / <i>NBL</i>                            | \$120.00          | 30(SN)      |
|                      |   | 4833.1            |             |
|                      | -10%: 4349.79   |                   |             |
|                      | Change rear lamp, reverse sensor, camera wiring labour      | \$200.00          | 40          |
|                      | Change rear windscreen labour                               | \$150.00          | 120         |
|                      | Knocking & welding body works                               | \$1000.00         | 400         |
|                      | Re-spray paint work   | \$950.00          | 600         |
|                      | Apply anti rust on affect parts                             | \$180.00          | X <i>NN</i> |
| <b>Amount Total:</b> |   | <b>\$11385.80</b> | 1160        |

5 Days. *Champion Repair*  
After repair photos.  
Gmo Riam - 82880282  
24/8/2021

5739.79

-20%: 4600