

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CS/CTI21008861/DTCQ2

**Date:**

20/12/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSNW00079812100

**Claimant Vehicle No :** SMY4223L**Insured Vehicle No :** YQ4211X

Date of Loss: 21/08/2021

Nature of Claim: TP

Claim No: SNM21D204672/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMY4223L**

Make &amp; Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU109564

Reg. Date: 26/03/2019 (Man. Year: 2019)

Chassis No: KMHD841CMKU879185

Colour: Black

Odometer: 43742 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 205/55 R16 | Rear Tyre Size:  | 205/55 R16 |
| Front Left Side:  | Kumho 5 mm | Rear Left Side:  | Kumho 5 mm |
| Front Right Side: | Kumho 5 mm | Rear Right Side: | Kumho 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 25,922.00         | 3,065.60          | 22,856.40         | 88.17         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,400.00          | 1,180.00          | 4,220.00          | 78.15         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>31,322.00</b>  | <b>4,245.60</b>   | <b>27,076.40</b>  | <b>86.45</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,400.00</b>   |                   |               |

|                        |           |          |           |       |
|------------------------|-----------|----------|-----------|-------|
| (S\$)                  | 31,322.00 | 3,400.00 | 27,922.00 | 89.15 |
| + GST 7.00/7.00% (S\$) | 2,192.54  | 238.00   | 1,954.54  | 89.15 |
| Nett Amount (S\$)      | 33,514.54 | 3,638.00 | 29,876.54 | 89.15 |

INSPECTION

|                             |            |               |                                                                                                             |
|-----------------------------|------------|---------------|-------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 24/08/2021 |               |                                                                                                             |
| Date Inspected:             | 24/08/2021 | Inspected At: | JWG International Pte Ltd (HQ)<br>Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint<br>Singapore 568047 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                                                             |

|           |            |          |                       |
|-----------|------------|----------|-----------------------|
| Adjuster: | BRYAN TANI | Manager: | DENISE TAY KWEE CHENG |
|-----------|------------|----------|-----------------------|

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                          |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 17 Dec 2021)            |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                        |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMY4223L)                                                                                                                                    |                                                          |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                          |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                          |

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition                      | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------|--------------------------------|-------------|--------------|
| 1   | 1   |          | *BONNET                                 | Not Necessary                  | 2,498.00 FL | *- FL        |
| 2   | 2   |          | *BONNET HINGE LH/RH                     | Not Necessary                  | 278.00 FL   | *- FL        |
| 3   | 1   |          | *BONNET INSULATOR                       | Not Necessary                  | 742.00 FL   | *- FL        |
| 4   | 1   |          | *BONNET LOCK                            | Not Necessary                  | 375.00 FL   | *- FL        |
| 5   | 1   |          | *BONNET SEAL                            | Not Necessary                  | 110.00 FL   | *- FL        |
| 6   | 1   |          | *HEAD LAMP LH /RH                       | O/S Cracked / N/SNot Necessary | 7,360.00 FL | *1,398.80 FL |
| 7   | 1   |          | *HEAD LAMP LOWER BRACKET LH /RH         | O/S Cracked / N/SNot Necessary | 580.00 FL   | *28.00 FL    |
| 8   | 2   |          | *HEAD LAMP ECU LH/RH                    | Not Necessary                  | 2,916.00 FL | *- FL        |
| 9   | 1   |          | *FRONT GRILLE                           | Cut                            | 790.00 FL   | *592.20 FL   |
| 10  | 1   |          | *FRONT GRILLE BASE                      | No such part                   | 618.00 FL   | *- FL        |
| 11  | 1   |          | *FRONT GRILLE LOGO                      | Serviceable                    | 89.00 FL    | *- FL        |
| 12  | 1   |          | *FRONT GRILLE CHROME                    | No such part                   | 401.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT BUMPER                           | Dented / Cracked               | 874.00 FL   | *574.00 FL   |
| 14  | 2   |          | *FRONT BUMPER SIDE RETAINER LH/RH       | Serviceable                    | 170.00 FL   | *- FL        |
| 15  | 1   |          | *FRONT BUMPER LOWER LID                 | Not Necessary                  | 692.00 FL   | *- FL        |
| 16  | 1   |          | *FRONT BUMPER SIGNAL LAMP LH/RH         | O/S Cut / N/S Not Necessary    | 820.00 FL   | *398.00 FL   |
| 17  | 2   |          | *FRONT BUMPER SIGNAL LAMP HOLDER LH/RH  | Not Necessary                  | 570.00 FL   | *- FL        |
| 18  | 1   |          | *FRONT BUMPER SIGNAL LAMP GARNISH LH/RH | O/S Cut / N/S Not Necessary    | 602.00 FL   | *164.00 FL   |
| 19  | 1   |          | *FRONT BUMPER SPONGE                    | Cracked / Broken               | 338.00 FL   | *173.00 FL   |
| 20  | 1   |          | *FRONT REINFORCEMENT BAR                | Not Necessary                  | 980.00 FL   | *- FL        |
| 21  | 1   |          | *FRONT SUPPORT PANEL                    | Repair                         | 1,890.00 FL | *- FL        |
| 22  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH        | Not Necessary                  | 342.00 FL   | *- FL        |
| 23  | 1   |          | *A/C CONDENSOR                          | Not Necessary                  | 1,784.00 FL | *- FL        |
| 24  | 1   |          | *A/C CONDENSOR HIGH PRESSURE PIPE       | Not Necessary                  | 874.00 FL   | *- FL        |
| 25  | 1   |          | *A/C CONDENSOR LOW PRESSURE PIPE        | Not Necessary                  | 391.00 FL   | *- FL        |
| 26  | 1   |          | *RADIATOR ASSY                          | Not Necessary                  | 1,993.00 FL | *- FL        |
| 27  | 1   |          | *RADIATOR FAN MOTOR                     | Not Necessary                  | 401.00 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No.                                          | Qty | Part No. | Particulars                   | Condition     | Repairer's                                                | Amount           |
|----------------------------------------------|-----|----------|-------------------------------|---------------|-----------------------------------------------------------|------------------|
| 28                                           | 1   |          | *RADIATOR FAN BLADE           | Not Necessary | 219.00 FL                                                 | *- FL            |
| 29                                           | 1   |          | *RADIATOR FAN COWLING         | Not Necessary | 452.00 FL                                                 | *- FL            |
| 30                                           | 1   |          | *FRONT BUMPER UNDER COVER     | Torn          | 525.00 FL                                                 | *289.70 FL       |
| 31                                           | 1   |          | *FRONT FENDER INNER SHIELD    | Torn          | 291.00 FL                                                 | *189.30 FL       |
| 32                                           | 1   |          | *FRONT GRILLE CLIPS           | Not Necessary | 50.00 FS                                                  | *- FS            |
| 33                                           | 1   |          | *FRONT BUMPER CLIPS           | Necessary     | 50.00 FS                                                  | *20.00 FS        |
| 34                                           | 1   |          | *FRONT BUMPER LOWER LID CLIPS | Not Necessary | 50.00 FS                                                  | *- FS            |
| 35                                           | 1   |          | *FRONT NO PLATE & GARNISH     | Not Necessary | 100.00 FS                                                 | *- FS            |
| 36                                           | 1   |          | *COOLANT                      | Not Necessary | 100.00 FS                                                 | *- FS            |
| 37                                           | 1   |          | *RIM                          | Not Necessary | 800.00 FS                                                 | *- FS            |
| F=Franchise part. S=SpcNett. L=ListItemDisc. |     |          |                               |               |                                                           |                  |
|                                              |     |          |                               |               | <b>Sub Total (S\$)</b>                                    | <b>32,115.00</b> |
|                                              |     |          |                               |               | <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> | <b>6,193.00</b>  |
|                                              |     |          |                               |               | <b>Total Parts (S\$)</b>                                  | <b>3,065.60</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                           | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                                       |          |                 |                 |
| 1                               | TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS                                         | New      | 300.00          | 0.00            |
| 2                               | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS                                               | New      | 2,000.00        | 600.00          |
| 3                               | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS                                                        | New      | 2,000.00        | 400.00          |
| 4                               | TO TUFF COAT DAMAGED AREAS                                                                            | New      | 200.00          | 0.00            |
| 5                               | TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS                                               | New      | 200.00          | 0.00            |
| 6                               | TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS                                                | New      | 200.00          | 0.00            |
| 7                               | TO CHECK & REFIX ALL ELECTRICAL WIRINGS                                                               | New      | 200.00          | 30.00           |
| 8                               | TO COMPUTERIZE DIAGNOSTIC FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS | New      | 300.00          | 150.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                       |          | <b>5,400.00</b> | <b>1,180.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >