

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008862/T1VF3N2**Date:** 18/01/2022**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLD8439C**Insured Vehicle No :** SMK2891U

Date of Loss: 13/08/2021

Nature of Claim: TP

Claim No: 4523891743SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLD8439C**

Make & Model: MAZDA 3, 1.6 (A)

Engine No: HIDDEN

Reg. Date: 29/06/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0342439

Colour: Red

Odometer: 127313 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,713.84	7,565.28	11,148.56	59.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,070.00	2,330.00	52.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,113.84	9,635.28	13,478.56	58.31
Approved Total (Overridden) (S\$)		7,700.00		
Nett Amount (S\$)	23,113.84	7,700.00	15,413.84	66.69

INSPECTION

Date of Assignment: 24/08/2021

Date Inspected: 24/08/2021 Inspected At:

TSL Auto Garage
Synergy Building, Kaki Bukit #01-44
Singapore 417800

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,023.90 FL	*917.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	796.70 FL	*574.00 FL
3	1		*REAR BUMPER SIDE RETAINER	N/s Cracked/O/s Not Necessary	159.60 FL	*79.80 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	308.60 FL	*- FL
5	1		*REAR BUMPER CENTER BRACKET	Necessary	19.80 FL	*19.80 FL
6	1		*REAR BUMPER TOW COVER	Cut	58.30 FL	*58.30 FL
7	2		*REAR BUMPER REVERSE SENSOR	Not Working	581.60 FL	*400.00 FL
8	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	170.60 FL	*- FL
9	1		*REAR BOOTLID	Repair	1,499.40 FL	*- FL
10	1		*REAR BOOTLID LAMP	N/s Cracked/O/s Not Necessary	1,130.80 FL	*499.00 FL
11	1		*REAR BOOTLID EMBLEM LOGO	Necessary	108.90 FL	*108.90 FL
12	1		*REAR BOOTLID EMBLEM MAZDA 3	Necessary	94.70 FL	*94.70 FL
13	1		*REAR BOOTLID EMBLEM SKYACTIVE	Necessary	87.50 FL	*87.50 FL
14	1		*REAR BOOTLID LOCK	Not Necessary	280.40 FL	*- FL
15	1		*REAR WEATHER STRIPE	Cut	172.80 FL	*172.80 FL
16	1		*REAR BOOTLID LOCK DETECTOR	Not Necessary	314.80 FL	*- FL
17	1		*REAR TAILLAMP	N/s Cracked/O/s Not Necessary	2,080.80 FL	*790.60 FL
18	1		*REAR END PANEL	Bent	676.30 FL	*557.00 FL
19	1		*REAR END PANEL TOP GARNISH	Deformed	180.30 FL	*180.30 FL
20	1		*FRONT BUMPER	Deformed	1,264.10 FL	*866.80 FL
21	1		*FRONT BUMPER REINFORCEMENT	Bent	750.10 FL	*459.20 FL
22	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	308.50 FL	*- FL
23	1		*FRONT BUMPER TOW COVER	Not Necessary	45.60 FL	*- FL
24	1		*FRONT BUMPER GARNISH	Deformed	285.60 FL	*285.60 FL
25	2		*FRONT BUMPER SIDE RETAINER	Necessary	133.00 FL	*133.00 FL
26	1		*FRONT BUMPER LOWER COVER	Not Necessary	189.20 FL	*- FL
27	2		*FRONT BUMPER FOG LAMP	Not Necessary	642.20 FL	*- FL
28	2		*FRONT BUMPER FOG LAMP OUTER COVER	Not Necessary	555.60 FL	*- FL
29	1		*FRONT GRILLE	Cracked	970.10 FL	*874.00 FL
30	1		*FRONT GRILLE UPPER MOULDING	Deformed	483.30 FL	*483.30 FL
31	1		*FRONT GRILLE CHROME MOULDING	Cracked	276.40 FL	*276.40 FL
32	1		*FRONT GRILLE LOGO	Necessary	104.90 FL	*104.90 FL
33	1		*FRONT GRILLE TOP GARNISH	Deformed	320.50 FL	*320.50 FL
34	1		*FRONT GRILLE TOP BRACKET	Cracked	89.10 FL	*89.10 FL
35	1		*BONNET	Not Necessary	1,458.40 FL	*- FL
36	2		*BONNET RUBBER SEAL	Not Necessary	63.80 FL	*- FL
37	1		*BONNET LOCK	Not Necessary	208.60 FL	*- FL
38	1		*FRONT SUPPORT PANEL	Not Necessary	886.90 FL	*- FL
39	1		*FRONT SUPPORT PANEL TIE BAR	Not Necessary	287.50 FL	*- FL
40	2		*FRONT SUPPORT PANEL SIDE GUIDE	Not Necessary	270.60 FL	*- FL
41	1		*FRONT SUPPORT PANEL UPPER GARNISH	Not Necessary	68.10 FL	*- FL
42	1		*FRONT SUPPORT PANEL LOWER GARNISH	Not Necessary	51.10 FL	*- FL
43	1		*FRONT HEADLAMP	O/s Cracked/N/s Not Necessary	3,246.60 FL	*812.00 FL
44	1		*FRONT HEADLAMP LOWER BRACKET	Os Necessary/Ns Not Necessary	174.20 FL	*87.10 FL
45	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
46	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
47	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
49	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

1/18/22, 9:28 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	23,289.80 9,431.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	4,575.96 1,866.32
					Total Parts (S\$)	18,713.84 7,565.28
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	1,000.00
2	LABOUR FOR SPRAYPAINTING	New	1,600.00	1,000.00
3	TO RUST PROOF/TUFF COAT ON REAR ACCIDENT AREAS	New	300.00	40.00
4	LABOUR FOR REMOVE & REFIX AIR CON CONDENSER TO FACILITATE THE REPAIR.TOP UP & VACCUM AIR CON GAS	New	200.00	0.00
5	WIRING CHECK	New	100.00	30.00
6	LABOUR FOR REMOVE & TRANSFER REAR BOOTLID FITTING	New	250.00	0.00
7	LABOUR FOR REMOVE & REFIX RADIATOR TO FACILITATE THE REPAIR	New	150.00	0.00
Gross Labour Cost (\$)			4,400.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >