

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008863/KUF3N2**Date:** 30/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900094223
Claimant Vehicle No :	SJC3765Y	Insured Vehicle No :	SJU9886Y
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	9014395256SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC3765Y	Engine No:	1NZX692645
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305047851
Reg. Date:	15/02/2008 (Man. Year: 2007)	Odometer:	204879 km
Colour:	Metallic Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,615.92	3,981.36	6,634.56	62.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,670.00	1,970.00	54.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,255.92	5,651.36	8,604.56	60.36
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	14,255.92	4,300.00	9,955.92	69.84

INSPECTION

Date of Assignment:	24/08/2021	
Date Inspected:	24/08/2021	Inspected At:
Estimated Period of Repair:	6.0 days	

160 SIN MING DRIVE #03-18/19
SIN MING AUTOCITY
SINGAPORE 575722
REPAIRER: EM SOLUTION PTE LTD

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Bent	1,257.60 FL	*1,099.20 FL
2	1		*FRONT DOOR OUTER HANDLE	Serviceable	181.60 FL	*- FL
3	1		*FRONT DOOR PROTECTOR	Dented	126.20 FL	*126.20 FL
4	1		*FRONT DOOR PROTECTOR MOULDING	Necessary	68.60 FL	*68.60 FL
5	1		*FRONT DOOR GLASS OUTER MOULDING	Serviceable	121.30 FL	*- FL
6	1		*FRONT DOOR GLASS RUN CHANNEL	Serviceable	155.90 FL	*- FL
7	1		*FRONT DOOR GLASS REGULATOR	Distorted	286.50 FL	*171.20 FL
8	1		*FRONT DOOR GLASS REGULATOR MOTOR	Jammed	381.90 FL	*351.60 FL
9	1		*FRONT DOOR INNER LOCK	Dented/Jammed	341.55 FL	*341.55 FL
10	1		*FRONT DOOR INNER TRIM BOARD	Mtg Cracked	631.50 FL	*631.50 FL
11	1		*FRONT DOOR INSULATION	Not Necessary	130.20 FL	*- FL
12	1		*FRONT DOOR W/STRIP	Serviceable	142.60 FL	*- FL
13	1		*CENTRE PILLAR-RH	Repair	891.50 FL	*- FL
14	1		*REAR DOOR-RH	Bent	1,257.60 FL	*1,025.10 FL
15	1		*REAR DOOR OUTER HANDLE	Serviceable	180.20 FL	*- FL
16	1		*REAR DOOR PROTECTOR	Dented	116.20 FL	*116.20 FL
17	1		*REAR DOOR PROTECTOR MOULDING	Necessary	66.30 FL	*66.30 FL
18	1		*REAR DOOR GLASS OUTER MOULDING	Serviceable	116.20 FL	*- FL
19	1		*REAR DOOR GLASS RUN CHANNEL	Serviceable	155.90 FL	*- FL
20	1		*REAR DOOR GLASS REGULATOR	Distorted	261.30 FL	*164.30 FL
21	1		*REAR DOOR GLASS REGULATOR MOTOR	Serviceable	381.90 FL	*- FL
22	1		*REAR DOOR GLASS GUIDE	Serviceable	132.50 FL	*- FL
23	1		*REAR DOOR 1/4 GLASS RUBBER	Serviceable	89.90 FL	*- FL
24	1		*REAR DOOR INSULATION	Not Necessary	130.20 FL	*- FL
25	1		*REAR DOOR INNER TRIM BOARD	Serviceable	631.50 FL	*- FL
26	1		*REAR DOOR W/STRIP	Serviceable	142.60 FL	*- FL
27	1		*REAR DOOR CHECKER	Serviceable	68.60 FL	*- FL
28	2		*REAR DOOR HINGES	Repair	111.20 FL	*- FL
29	1		*REAR FENDER	Repair	899.60 FL	*- FL
30	1		*REAR BUMPER	Mtg Cracked	520.60 FL	*427.90 FL
31	1		*REAR BUMPER SIDE RETAINERS	O/s Distorted	91.00 FL	*45.50 FL
32	1		*REAR BUMPER SPLASH SHIELD	Serviceable	124.65 FL	*- FL
33	1		*REAR SHOCK ABSORBER-RH	Serviceable	281.50 FL	*- FL
34	1		*REAR AXLE BEAM	Serviceable	1,655.90 FL	*- FL
35	1		*REAR WHEEL HUB BEARING	Not Necessary	415.60 FL	*- FL
36	1		*SET F/R DOOR VISOR	Necessary	280.00 FS	*120.00 FS
37	1		*SET FRONT DOOR BLACK TAPE	Necessary	80.00 FS	*50.00 FS
38	1		*SET REAR DOOR BLACK TAPE	Necessary	80.00 FS	*50.00 FS
39	1		*REAR SPORT WHEEL-RH	Dented	450.00 FS	*250.00 FS
40	1		*REAR TYRE-RH	Serviceable	280.00 FS	*- FS
41	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,752.90	5,140.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,136.98	1,158.79
Total Parts (\$\$)	10,615.92	3,981.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR UNDERCARRIAGE	New	350.00	0.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	0.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
4	TO RESPRAY UNDERCOATING	New	150.00	60.00
5	TO RESPRAY PAINTING AND ETC	New	1,400.00	900.00
6	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	650.00
Gross Labour Cost (\$)			3,640.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >