9/6/21, 9:15 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21008867/EQCN2

06/09/2021 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00104942000

**Claimant Vehicle** 

SHA9346T

Insured

**GBE3753R** 

No:

Vehicle No:

Date of Loss:

21/08/2021

Nature of Claim: TP

Claim

SNM21D204666/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SHA9346T** Reg No:

HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: Make & Model: D4FDGU662195

Reg. Date: 11/08/2016 (Man. Year: 2016) Chassis No:

Odometer:

KMHLB41UMGU092601 372211 km

Yes

Colour: Yellow 1685 cc

**Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Rear Left Side: West Lake 5 mm West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,288.13	2,541.13	5,747.00	69.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	1,060.00	2,900.00	73.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	12,248.13	3,601.13	8,647.00	70.60
Approved Total (Overridden) (S\$	)	2,800.00		
(S\$	12,248.13	2,800.00	9,448.13	77.14
+ GST 7.00/7.00% (S\$	857.37	196.00	661.37	77.14
Nett Amount (S\$	13,105.50	2,996.00	10,109.50	77.14

**INSPECTION** 

Date Inspected:

Date of Assignment: 24/08/2021

10 SECTOR C SIN MING INDUSTRIAL EST.

24/08/2021 Inspected At: #01-20, SINGAPORE 575645

REPAIRER: DING AUTOMOTIVE PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/6/21, 9:15 AM Adjuster Report

### **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHA9346T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Broken	599.68 FL	*599.68 FL
2	1		*FRONT BUMPER LOWER LIP	Not Necessary	83.67 FL	*- FL
3	1		*FRONT LH BUMPER RETAINER	Broken	48.93 FL	*48.93 FL
4	1		*FRONT LH BUMPER SIDE MOUNTING BRACKET	Not Necessary	38.83 FL	*- FL
5	1		*FRONT BUMPER ENERGY ABSORBER	Not Necessary	98.60 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	484.40 FL	*- FL
7	1		*FRONT LH BUMPER FOG LAMP GRILLE COVER	Not Necessary	288.55 FL	*-FL
8	1		*FRONT LH BUMPER AIR DUCT	Not Necessary	133.66 FL	*- FL
9	1		*FRONT LH HEADLAMP	Cut	1,808.60 FL	*1,808.60 FL
10	1		*FRONT LH HEADLAMP BRACKET	Not Necessary	52.33 FL	*- FL
11	1		*FRONT BONNET	Repair	1,812.68 FL	*- FL
12	1		*FRONT LH FENDER PANEL	Dented	656.70 FL	*656.70 FL
13	1		*FRONT LH FENDER LINER	Not Necessary	186.30 FL	*- FL
14	1		*RADIATOR GRILLE	Not Necessary	1,110.10 FL	*- FL
15	1		*RADIATOR GRILLE EMBLEM	Not Necessary	142.84 FL	*- FL
16	1		*RADIATOR GRILLE CHROME MOULDING	Not Necessary	121.77 FL	*- FL
17	1		*FRONT LH WHEEL RIM COVER	Not Necessary	265.20 FL	*-FL
18	1		*FRONT BUMPER UPPER STRIP	Not Necessary	98.60 FL	*- FL
19	1		*AIR CLEANER INTAKE RESONATOR	Not Necessary	198.67 FL	*-FL
20	1		*FRONT END MODULE CARRIER ASSY	Not Necessary	986.30 FL	*- FL
21	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
22	1		*SET FRONT BUMPER RIVET	Necessary	60.00 FS	*20.00 FS
23	1		*FRONT TYRE 205/60/16	Not Necessary	350.00 FS	*- FS
24	1		*SET FRONT FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
25	1		*SET RADIATOR GRILLE CLIP	Not Necessary	60.00 FS	*- FS
26	4		*RADIATOR COOLANT	Not Necessary	300.00 FS	*- FS
F=Fra	ınchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	10,131.41	3,163.91
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,843.28	622.78	
				Total Parts (S\$)	8,288.13	2,541.13

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	New	1,400.00	400.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	New	300.00	0.00
4	TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	260.00	30.00
5	TO READJUST AND REALIGN HEADLAMP AIM	New	140.00	0.00
6	TO REMOVE AND REFIT A/C CONDENSER,RADIATOR AND INTERCOOLER TO ENABLE REPAIR	New	280.00	0.00
7	TO VACUUM AND TOPUP AIR COND GAS FOR A/C CONDENSER AND INTERCOOLER	New	250.00	0.00
8	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	160.00	0.00
9	TO RESPRAY FRONT BUMPER	New	250.00	200.00
10	TO RESPRAY FRONT FENDER PANEL	New	250.00	200.00
11	TO RESPRAY FRONT BONNET	New	250.00	200.00
12	TO RESPRAY FRONT WHEEL RIM COVER	New	250.00	0.00
	Gross Labour Cost (S\$)		3,960.00	1,060.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >