



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 4663D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RH FRONT FENDER MUDFLAP	NOT NECESSARY	106.50	-
	LESS 25% DISCOUNT		-26.63	-
			79.87	-
1	BODY STICKER (SN)	NECESSARY	180.00	120.00
	LESS 25% DISCOUNT		-45.00	-
			135.00	120.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	COMPANY REGISTRATION STICKER (SN)	NECESSARY	30.00	30.00
			30.00	30.00
<b><u>LABOUR</u></b>				
	TO KNOCK & STRAIGHTEN THE DAMAGED PANELS,REMOVE & RENEW DAMAGED PARTS,ADJUST & REALIGN THE SAME.		400.00	100.00
	TO SPRAY PAINT ALL AFFECTED AREAS.		600.00	400.00
			1,000.00	500.00
<b>GRAND TOTAL</b>			<b>1,244.87</b>	<b>650.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>				<b>650.00</b>

Report Ref No. CS/SMO21008868/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.