

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	F	Ref:	CS/SMO21008868/Atf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	С	Date:	22/11/2021	
			C	Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMZ 8564X	Veh. Inspected		GBK 4663D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2102537/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		24/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTFHT02P009990185	Colour		WHITE	
	Odometer	50317 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15C	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15C	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/08/2021	Inspection Date		27/08/2021	
	Survey held at	eld at AUTO BAY @ KAKI BUKIT AVENUE 6 #01-04				
	Repairer	Repairer KT GARAGE PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					