



陳林澤嗎私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SMM9252H
Date of Accident : 20 August 2021

Messrs Transportation OTG

Date : 23 August 2021

Estimate To Repair PC3639H - Toyota Hiace Commuter GL 3.0 A
Chassis No : KDH2230023396

Reg! Marcus - Lkh
24/08/2021 10:00h

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	front bumper DIS	\$ 1,050.00 ✓
02	1 pc	front bumper reinforcement bottom 11 X	\$ 345.00 X
03	2 ps	front bumper side holder @ \$150.00 17C 115.00	\$ 300.00 1PC
04	4 ps	front bumper side holder clips @ \$4.50 11 X	\$ 18.00 X
05	2 ps	front bumper air scoop @ \$39.00 11 X	\$ 78.00 X
06	1 pc	n/s headlamp one ✓	\$ 700.00 ✓
07	1 pc	n/s front door DO ✓	\$ 1,867.90 ✓
08	1 pc	n/s front door hinge top 11 X	\$ 115.00 X
09	1 pc	n/s front door hinge bottom 11 X	\$ 115.00 X
10	1 pc	n/s front door window glass channel weatherstrip with outer 11 X	\$ 79.10 X
11	1 pc	n/s front door weatherstrip 11 X	\$ 220.00 X
			\$ 4,888.00
Less 25 %			\$ 1,222.00
			\$ 3,666.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 50.00 20
02		To transfer of door fittings and perform water seepage test.	\$ 100.00 50
03		To rust-proofing of the affected areas.	\$ 120.00 30
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00 300
05		Putty and spray painting of the affected portion.	\$ 700.00 300
			\$ 1,670.00
Total			\$ 5,336.00

not full amount
Lkh

24/8/21
2/s \$2400/
Wheephe Ather rep
2 days.
Lkh Cecilia

p- 3086.31
25%
2314.73
700
3014.73
25%
2411.28

LKK Auto Consultants hence notify the Repaired of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature: