

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21008870/AQF3E2

Date: 03/12/2021

REFERENCE

Insured/Claimant: J MUNTRAMOORTHY Policy No: MPC21P00088200
Date of Loss: 18/08/2021 Nature of Claim: OD Claim No: DMPC2100281H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ7646L**
Make & Model: MERCEDES-BENZ CLA180, 1.6 (A) Engine No: 27091031608374
Reg. Date: 18/05/2018 (Man. Year: 2018) Chassis No: WDC1569422J500053
Colour: Blue Odometer: 69807 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,754.20	4,407.70	346.50	7.29
Miscellaneous Items	60.00	60.00	0.00	0.00
Labour	2,120.00	1,410.00	710.00	33.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,934.20	5,877.70	1,056.50	15.24
+ GST 7.00/7.00% (S\$)	485.39	411.44	73.95	15.24
Nett Amount (S\$)	7,419.59	6,289.14	1,130.45	15.24

INSPECTION

Date of Assignment: 24/08/2021 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 25/08/2021 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
Estimated Period of Repair: 6.0 days 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2021)
Parts:	143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ7646L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE LOGO (WCP)	Not Necessary	40.00 F	*- F
2	1		*REAR BUMPER (WCP)	Distorted	750.00 F	*750.00 F
3	1		*REAR BUMPER RETAINER RH (WCP)	Necessary	22.00 F	*22.00 F
4	10		*REAR BUMPER CLIP (WCP)	Necessary	45.00 F	*45.00 F
5	1		*REAR BUMPER LOWER (MATT BLACK) (WCP)	Deformed	420.00 F	*420.00 F
6	1		*REAR BUMPER CORNER RH PARKING SENSOR (WCP)	Cracked	170.00 F	*170.00 F
7	1		*TAIL LAMP RH (WCP)	Cracked	490.00 F	*490.00 F
8	1		*REAR FENDER RH (WCP)	Distorted	1,650.00 F	*1,650.00 F
9	1		*REAR FENDER INNER AIR DUCT RH (WCP)	Cracked	35.00 F	*35.00 F
10	1		*REAR FENDER PROTECTOR RH (WCP)	Torn	175.00 F	*175.00 F
11	1		*REAR FENDER INNER COWLING RH (WCP)	Not Necessary	155.00 F	*- F
12	10		*INNER COWLING CLIP (WCP)	Not Necessary	45.00 F	*- F
13	1		*REAR BUMPER CENTER TOP CHROME PLATE (WCP)	Necessary	170.00 F	*170.00 F
14	1		*REAR GATE GLA 180 PLATE (WCP)	Not Necessary	75.00 F	*- F
Supplementary #1						
15	1		*REAR RH TAIL LAMP LOWER BRACKET (WCP)	Cracked	65.00 F	*65.00 F
16	1		*TAIL LAMP CLIPS (WCP)	Necessary	5.00 F	*5.00 F
17	1		*REAR RH TAIL LAMP SCREW (WCP)	Necessary	10.00 F	*10.00 F

F=Franchise part.

Sub Total (S\$)	4,322.00	4,007.00
+ Margin on L,N Items 10.00/10.00% (S\$)	432.20	400.70
Total Parts (S\$)	4,754.20	4,407.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR FENDER SEALANT (NECESSARY)	60.00	60.00
Sub Total (\$\$)			60.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	40.00	30.00
2	REMOVE & REFIX CUSHION AND SEATS	New	180.00	80.00
3	LABOUR CHARGE	New	1,000.00	700.00
4	SPRAY PAINTING	New	900.00	600.00
Gross Labour Cost (\$\$)			2,120.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >