

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 29 Nov 2021

Preliminary Advice

Vehicle No	: SLZ7646L	Accident Date	: 18/08/2021
Make	: MERCEDES-BENZ CLA180	Policy No.	: MPC21P00088200
Assignment Date	: 24/08/2021	Excess	: S\$0.00
Date of Inspection	: 25/08/2021	Est. Duration of Repair	: 6
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,934.20	(ESTIMATE \$6,846.20 + SUPPLEMENTARY \$88.00)
Revised Amount	:S\$	5,877.70	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	5,877.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	49,943.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,057.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.