

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCJ 1828J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY (CONSISTENT)	DEFORMED / TORN	1,221.00	1,221.00
1	REAR BUMPER LEFT BRACKET (CONSISTENT)	CRACKED	73.00	73.00
1	REAR BUMPER LEFT RETAINER (CONSISTENT)	TWISTED	78.00	78.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	387.00	387.00
1	REAR BUMPER TOW COVER (CONSISTENT)	NOT NECESSARY	89.00	-
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	DEFORMED	197.00	197.00
1	REAR LEFT TAILLAMP (CONSISTENT)	CRACKED	454.00	454.00
1	REAR TAILGATE ASSY (CONSISTENT)	NOT NECESSARY	1,810.00	-
1	REAR TAILGATE INNER BOARD (CONSISTENT)	NOT NECESSARY	279.00	-
1	REAR TAILGATE LOCK MECHANISM (CONSISTENT)	NOT NECESSARY	251.00	-
1	REAR TAILGATE 'CYCLE AND CARRIAGE' EMBLEM (CONSISTENT)	NOT NECESSARY	68.00	-
1	REAR TAILGATE 'A180' EMBLEM (CONSISTENT)	NOT NECESSARY	98.00	-
1	REAR TAILGATE CENTRE LOGO (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	189.00	-
1	REAR END LOWER PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	163.00	-
1	REAR END LOWER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	865.00	-
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NOT NECESSARY	288.00	-
1	REAR LEFT FENDER (CONSISTENT)	NOT NECESSARY	1,620.00	-
1	REAR LEFT FENDER INNER COWLING (CONSISTENT)	NOT NECESSARY	195.00	-
1	REAR LEFT FENDER INNER GARNISH (CONSISTENT)	NOT NECESSARY	426.00	-
	LESS 10% DISCOUNT		-887.10	-241.00
			7,983.90	2,169.00
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	60.00
8	REAR TAILGATE INNER BOARD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
4	REAR END LOWER PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR END LOWER PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	120.00	-

Report Ref No. CC4/ASM21008871/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
4	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	N/S SHORTED	1,200.00	180.00
1	REAR NO PLATE WITH GARNISH (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
4	REAR LEFT FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
6	REAR LEFT FENDER INNER GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR LEFT FENDER SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			1,820.00	240.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR LEFT AFFECTED AREA AND REPLACE REAR LEFT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR END LOWER PANEL .		1,000.00	400.00
	TO PUTTY AND SPRAY PAINTING REAR LEFT PORTION .		1,000.00	600.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	20.00
	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM .	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR LEFT AFFECTED AREA.	NOT NECESSARY	140.00	-
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR .		80.00	50.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR.	NOT NECESSARY	140.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			2,910.00	1,150.00
	GRAND TOTAL		12,713.90	3,559.00



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		2,800.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM21008871/Ura3q2

CHUA KANG SENG

Licensed Appraiser