



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 7274Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RIGHT DOOR ASSY	GRAZED / DENTED	973.00	973.00
1	REAR RIGHT DOOR ASSY	GRAZED / DENTED	903.00	903.00
2	REAR RIGHT DOOR HINGES	TO REPAIR SEE LABOUR	176.00	-
1	REAR RIGHT DOOR CHECKER LINKAGE	TO REPAIR SEE LABOUR	179.00	-
1	REAR RIGHT DOOR OUTER HANDLE	BENT / NECESSARY	175.00	175.00
1	REAR RIGHT DOOR LOCK MECHANISM	BENT	125.00	125.00
1	REAR RIGHT DOOR REGULATOR WITH MOTOR ASSY	MALFUNCTION	347.00	347.00
1	REAR RIGHT DOOR WEATHERSTRIP	WARPED / CUT	124.00	124.00
1	REAR RIGHT DOOR GLASS	GRAZED / CUT	345.00	345.00
1	REAR RIGHT DOOR GLASS CHROME MOULDING	GRAZED / CUT	279.00	279.00
	LESS 10% DISCOUNT		-362.60	-327.10
			3,263.40	2,943.90
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RIGHT LOWER SPOILER (SN)	WARPED / BENT	880.00	550.00
10	REAR RIGHT LOWER SPOILER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR RIGHT LOWER SPOILER SEALANT (SN)	NECESSARY	80.00	50.00
			990.00	630.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT, REAR RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT AND REAR RIGHT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR RIGHT DOOR HINGES AND REAR RIGHT DOOR CHECKER LINKAGE.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AND REAR RIGHT PORTION.		1,200.00	600.00
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AND REAR RIGHT AFFECTED AREA.		120.00	40.00
	TO REMOVE AND INSTALL REAR RIGHT DOOR LOCK MECHANISM.		80.00	60.00
	TO CHECK DOOR CENTRE LOCKING FOR FUNCTION.		80.00	30.00

Report Ref No. CS1/LAW21008876/T1tce2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER REAR RIGHT DOOR GLASS TO NEW DOOR.		80.00	60.00
	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR.		80.00	60.00
			2,840.00	1,450.00
GRAND TOTAL			7,093.40	5,023.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS1/LAW21008876/T1tce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.