

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21008878/BTF3E2

Date: 01/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLP6184L **Insured Vehicle No :** SLH9587E
Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: MFL2021D0003571

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP6184L**
Make & Model: HYUNDAI TUCSON, 2.0 GLS (A) Engine No: G4NAHU411796
Reg. Date: 13/06/2017 (Man. Year: 2017) Chassis No: KMHJ3813MJU490871
Colour: Brown Odometer: 85358 km
Engine Capacity: 1999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm
Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,433.13	1,478.45	3,954.68	72.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	800.00	1,250.00	60.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,483.13	2,278.45	5,204.68	69.55
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	7,483.13	1,800.00	5,683.13	75.95
+ GST 7.00/7.00% (S\$)	523.82	126.00	397.82	75.95
Nett Amount (S\$)	8,006.95	1,926.00	6,080.95	75.95

INSPECTION

Date of Assignment: 24/08/2021
Date Inspected: 25/08/2021 Inspected At: JP Conceptz Pte Ltd (HQ)
160 Sin Ming Drive #07-07, AutoCity
Singapore 575722
Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2021)
Parts:	M1-SUV	HYUNDAI TUCSON 2.0 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP6184L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET INNER LOCK	Repair	66.30 F	*- FL
2	1		*HEADLAMP ASSEMBLY N/S	Cut	2,678.18 F	*885.00 FL
3	1		*HEADLAMP LOWER BRACKET N/S	Serviceable	36.60 F	*- FL
4	1		*FRONT BUMPER	Cut	570.42 F	*460.00 FL
5	1		*FRONT BUMPER FOG LAMP ASSEMBLY N/S	Serviceable	201.13 F	*- FL
6	1		*FRONT BUMPER FOG LAMP GARNISH N/S	Serviceable	51.01 F	*- FL
7	1		*FRONT BUMPER LCD GUIDE LAMP ASSEMBLY N/S	Serviceable	182.42 F	*- FL
8	1		*FRONT BUMPER LCD GUIDE LAMP GARNISH N/S	Serviceable	37.14 F	*- FL
9	1		*FRONT BUMPER LOWER GARNISH N/S	Not Damaged	64.10 F	*- FL
10	1		*FRONT BUMPER SIDE RETAINER N/S	Necessary	31.42 F	*31.42 FL
11	1		*FRONT FENDER N/S	Dented	434.14 F	*434.14 FL
12	1		*FRONT FENDER WHEEL ARCH GARNISH N/S	Serviceable	211.47 F	*- FL
13	1		*FRONT FENDER INNER SHIELD N/S	Serviceable	88.80 F	*- FL
14	1		*SET FRONT BUMPER CLIP / FASTENER	Necessary	50.00 FS	*30.00 FS
15	1		*FRONT FENDER WHEEL ARCH CLIP / FASTENER N/S	Not Necessary	30.00 FS	*- FS
16	1		*FRONT ALLOY RIM N/S	Serviceable	450.00 FS	*- FS
17	1		*FRONT TYRE [HANKOOK : 225/60R17/N/S]	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,433.13	1,840.56
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	362.11
Total Parts (\$\$)	5,433.13	1,478.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTION INCLUDING TO FOCUS HEADLAMPS	New	50.00	0.00
2	TO DISMANTLE / INSTALL AIR CONDITIONER CONDENSER & RADIATOR ASSEMBLY, PIPES & HOSES ETC. TO FACILITATE REPAIRS & REFILL WITH REFRIGERANT [CLIMATIZER R134A SPECIFICATION] & COOLANT RESPECTIVELY	New	180.00	0.00
3	TO CORRECT FRONT WHEEL GEOMETRY INCLUDING TO OSCILLATE / EQUIPOISE N/S ALLOY RIM / TYRE TO SPECIFICATIONS	New	120.00	0.00
4	TO DISMANTLE / RENEW THE FRONT ACCIDENT DAMAGED PORTIONS. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DISMENSIONS	New	850.00	400.00
5	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT }	New	850.00	400.00
6	TO DO RUSTPROOFING AND CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS }	New	0.00	0.00
Gross Labour Cost (S\$)			2,050.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >