

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008881/KTCE2

Date: 07/10/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00116312000		
Claimant Vehicle No :	SKU6514D	Insured Vehicle No :	GBC9449R		
Date of Loss:	20/08/2021	Nature of Claim:	TP	Claim No:	SNM21D204627/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6514D	Engine No:	K24W71011026
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Chassis No:	JHMRC1890FC202213
Reg. Date:	06/08/2015 (Man. Year: 2015)	Odometer:	232809 km
Colour:	Metallic Grey		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,412.00	1,412.00	0.00	0.00
Miscellaneous Items	170.00	170.00	0.00	0.00
Labour	386.40	239.40	147.00	38.04
Paintwork Labour	483.67	463.99	19.68	4.07
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,452.07	2,285.39	166.68	6.80
+ GST 7.00/7.00% (S\$)	171.64	159.98	11.66	6.79
Nett Amount (S\$)	2,623.71	2,445.37	178.34	6.80

INSPECTION

Date of Assignment:	24/08/2021	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	24/08/2021	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2021)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU6514D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		1,332.00 F	*1,332.00 F
<u>Supplementary #1</u>						
2	1		*R/R BUMPER COVER	Cracked	70.00 F	*70.00 F
3	1		*TAILGATE STOPPER RH	Missing	10.00 F	*10.00 F
					Total Parts (S\$)	1,412.00
						1,412.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	170.00	170.00
Sub Total (\$\$)			170.00	170.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	483.67	463.99
<u>Labour Items</u>				
2	Total of Labour	New	386.40	239.40
Gross Labour Cost (\$\$)			870.07	703.39

Report was unsubmitted during this print-out.

< END OF ESTIMATES >