

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21008884/BTF3N2**Date:** 28/09/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKQ2153J**Insured Vehicle No :** SLB2425S

Date of Loss: 20/08/2021

Nature of Claim:

TP

Claim No: 3157462036SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKQ2153J**

Make &amp; Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)

Engine No: A555J836N13B16A

Reg. Date: 12/11/2014 (Man. Year: 2014)

Chassis No: WBA3A12040J722396

Colour: Blue

Odometer: 143237 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 255/40R18

Rear Tyre Size:

225/45R18

Front Left Side: Yokohama 5 mm

Rear Left Side:

Goodyear 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment: 24/08/2021

Date Inspected: 25/08/2021 Inspected At:

Mje Motor

7 Sin Ming Industrial Estate Sector C, #01-94

Singapore 575642

Estimated Period of Repair: 4.0 days

**Adjuster:** Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$56,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
4	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
5	2		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
6	1		*REAR END PANEL	Dented	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
8	1		*REAR LH TAILLAMP GARNISH	Broken	0.00 F	*- F
9	1		*CENTRE EXHAUST PIPE ASSY	Dented	0.00 F	*- F
10	1		*REAR EXHAUST CHROME PIPE	Dented	0.00 F	*- F
11	1		*REAR LH FENDER	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >