

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008887/GVCN2**Date:** 13/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00047922100

Claimant Vehicle No : SMR6730M **Insured Vehicle No :** GBK7023G

Date of Loss: 22/08/2021 Nature of Claim: TP Claim No: SNM21D204697/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR6730M**

Make & Model: TOYOTA SIENTA, 1.5 CVT ELEGANCE (A) Engine No: 2NRX522799

Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: MHFZ28H3800067075

Colour: Black Odometer: 35244 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R16 Rear Tyre Size: 195/50R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,277.60	3,969.90	4,307.70	52.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,101.58	6,171.58	3,930.00	38.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,379.18	10,141.48	8,237.70	44.82
+ GST 7.00/7.00% (S\$)	1,286.54	709.90	576.64	44.82
Nett Amount (S\$)	19,665.72	10,851.38	8,814.34	44.82

INSPECTION

Date of Assignment: 24/08/2021

Date Inspected: 26/08/2021 Inspected At: Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2021)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR6730M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LENS & BODY,RR	Not Necessary	369.40 FS	*- FS
2	1		*LENS & BODY,RR	Cracked	369.40 FS	*369.40 FS
3	2		*CLIP,BACK DOOR	Not Necessary	7.20 FS	*- FS
4	1		*LENS & BODY,RR	Not Necessary	264.30 FS	*- FS
5	1		*LENS & BODY,RR	Not Necessary	264.30 FS	*- FS
6	1		*BACK SENSOR (218,ATTITUDE BLAC)	Not Necessary	172.40 FS	*- FS
7	1		*REFLECTOR ASSY,REFL	Not Necessary	60.40 FS	*- FS
8	1		*REFLECTOR ASSY,REFL	Not Necessary	60.40 FS	*- FS
9	1		*LAMP ASSY,RR FOG	Not Necessary	236.70 FS	*- FS
10	1		*BRACKET,FOG LAMP	Not Necessary	56.50 FS	*- FS
11	1		*ANTENNA,ELECTRICAL	Not Necessary	72.60 FS	*- FS
12	1		*COVER,RR BUMPER,L	Deformed	319.20 FS	*319.20 FS
13	1		*EXTENSION,RR BUMPER	Cut	191.80 FS	*191.80 FS
14	1		*PLATE,RR BUMPER,NO	Not Necessary	21.10 FS	*- FS
15	1		*EXTENSION,RR BUMPER	Not Necessary	130.30 FS	*- FS
16	1		*EXTENSION,RR BUMPER	Not Necessary	130.30 FS	*- FS
17	10		*CLIPS	Necessary	41.00 FS	*41.00 FS
18	1		*SUPPORT,RR BUMPER S	Not Necessary	74.10 FS	*- FS
19	1		*SUPPORT,RR BUMPER S	Not Necessary	74.10 FS	*- FS
20	1		*RETAINER,RR BUMPER	Not Necessary	71.10 FS	*- FS
21	1		*RETAINER,RR BUMPER	Not Necessary	71.10 FS	*- FS
22	1		*PANEL SUB-ASSY,LWR	Repair	702.90 FS	*- FS
23	1		*PANEL SUB-ASSY,BODY	Repair	438.20 FS	*- FS
24	1		*COVER,DECK TRIM,RR	Not Necessary	155.90 FS	*- FS
25	1		*GLASS SUB-ASSY,BACK	Necessary	1,041.50 FS	*1,041.50 FS
26	2		*SIKA 182010 SIKA TACK GO! (BLA)	Necessary	216.00 FS	*216.00 FS
27	1		*SIKA 207.G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
28	2		*DAM,BACK WINDOW GLA	Necessary	25.00 FS	*25.00 FS
29	1		*PANEL SUB-ASSY BACK	Buckled	1,142.50 FS	*1,142.50 FS
30	1		*WEATHERSTRIP,BACK D	Not Necessary	376.00 FS	*- FS
31	1		*LOCK ASSY,BACK DOOR	Not Necessary	472.40 FS	*- FS
32	1		*STRIKER ASSY,BACK D	Not Necessary	26.00 FS	*- FS
33	1		*FRONT BONNET EMBLEM	Necessary	72.20 FS	*72.20 FS
34	1		*PLATE,BACK DOOR NAM	Necessary	35.80 FS	*35.80 FS
35	1		*PLATE,BACK DOOR NAM	Necessary	53.70 FS	*53.70 FS
36	1		*GARNISH SUB-ASSY,BA	Deformed	231.80 FS	*231.80 FS
37	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,277.60** **3,969.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
2	SUPPLY SEALANT FOR REAR TAILGATE	New	60.00	60.00
3	TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM	New	400.00	400.00
4	TO CHECK WIRING AND LIGHTING TO WATER TEST FOR LEAK	New	122.40	122.40
5	R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION	New	180.00	180.00
6	R/I REAR WINDSCREEN TO FACILITATE REPAIRS AND TEST FUNCTION	New	396.00	396.00
7	TO TRANSFER REAR TAILGATE BOARD,WIPER MOTOR AND OTHER ATTACHMENT TO FACILITATE REPAIRS	New	360.00	360.00
8	R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILITATE REPAIRS	New	360.00	360.00
9	TO REPLACE REAR ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS	New	4,320.00	2,160.00
10	TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS	New	3,540.00	1,770.00
11	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	New	183.18	183.18
Gross Labour Cost (\$)			10,101.58	6,171.58

Report was unsubmitted during this print-out.

< END OF ESTIMATES >