

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008888/ETCE2

Date: 01/10/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004192100  
Claimant Vehicle No: SHA9113Z Insured Vehicle No: SLD3980M  
Date of Loss: 14/08/2021 Nature of Claim: TP Claim No: SNM21D204694/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA9113Z  
Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDEU440992  
Reg. Date: 17/03/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU085506  
Colour: Yellow Odometer: 656284 km  
Engine Capacity: 1685 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Sailun 4 mm Rear Left Side: Sailun 4 mm  
Front Right Side: Sailun 4 mm Rear Right Side: Sailun 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,821.45	232.40	1,589.05	87.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	950.00	2,930.00	75.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,701.45</b>	<b>1,182.40</b>	<b>4,519.05</b>	<b>79.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>950.00</b>		
<b>(S\$)</b>	5,701.45	950.00	4,751.45	83.34
<b>+ GST 7.00/7.00% (S\$)</b>	399.10	66.50	332.60	83.34
<b>Nett Amount (S\$)</b>	<b>6,100.55</b>	<b>1,016.50</b>	<b>5,084.05</b>	<b>83.34</b>

### INSPECTION

Date of Assignment: 24/08/2021  
Date Inspected: 25/08/2021 Inspected At: Ding Automotive Pte Ltd (HQ)  
31 CORPORATION ROAD  
Singapore 649825  
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 01 Oct 2021)

**Parts:** 143    HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHA9113Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	599.68 FL	*- FL
2	1		*REAR RH BUMPER RETAINER	Not Necessary	58.60 FL	*- FL
3	1		*REAR BUMPER ENERGY ABSORBER	Not Necessary	99.62 FL	*- FL
4	1		*REAR BUMPER LOWER	Not Necessary	228.40 FL	*- FL
5	1		*REAR WHEEL RIM COVER	Cut	265.50 FL	*265.50 FL
6	1		*REAR RH FENDER LINER	Not Necessary	178.88 FL	*- FL
7	1		*REAR RH QUARTER PANEL AIR VENT	Not Necessary	89.88 FL	*- FL
8	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*20.00 FS
9	1		*REAR BUMPER LOWER CLIP	Not Necessary	70.00 FS	*- FS
10	1		*SET REAR FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
11	1		*ROCKER PANEL MOULDING CLIP	Not Necessary	60.00 FS	*- FS
12	1		*REAR DOOR COMFORT DELGRO STICKER	Not Necessary	140.00 FS	*- FS
13	1		*REAR DOOR GOOGLE PLAY STORE APP STORE STICKER	Not Necessary	140.00 FS	*- FS
14	1		*SET TAILLAMP GUIDE CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,125.56</b>	<b>285.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	304.11	53.10
<b>Total Parts (\$\$)</b>	<b>1,821.45</b>	<b>232.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	New	1,400.00	400.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	New	280.00	0.00
4	TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	220.00	30.00
5	TO REFIT REAR REVERSE SENSOR	New	150.00	30.00
6	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	160.00	60.00
7	TO RESPRAY REAR BUMPER	New	250.00	200.00
8	TO RESPRAY REAR BUMPER LOWER	New	250.00	0.00
9	TO RESPRAY REAR END PANEL	New	250.00	0.00
10	TO RESPRAY REAR QUARTER PANEL	New	250.00	200.00
11	TO RESPRAY REAR DOOR PANEL	New	250.00	0.00
12	TO RESPRAY SIDE SKIRT RH	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,880.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >