

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008891/BVCN2**Date:** 06/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00085692102

Claimant Vehicle No : SMP3688H **Insured Vehicle No :** GBC8561E

Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: SNM21D204656/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP3688H**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1960673

Reg. Date: 22/06/2017 (Man. Year: 2017) Chassis No: JTDGG20W40J007070

Colour: Blue Odometer: 195482 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,739.90	7,976.10	3,763.80	32.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,110.00	1,110.00	34.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,959.90	10,086.10	4,873.80	32.58
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	14,959.90	8,000.00	6,959.90	46.52
+ GST 7.00/7.00% (\$\$)	1,047.19	560.00	487.19	46.52
Nett Amount (\$\$)	16,007.09	8,560.00	7,447.09	46.52

INSPECTION

Date of Assignment: 24/08/2021

Date Inspected: 25/08/2021 Inspected At: Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP3688H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,436.80 FL	*1,436.80 FL
2	1		*REAR BOOT LOGO	Necessary	104.50 FL	*66.00 FL
3	2		*REAR BOOT LAMP L+R	Broken	786.80 FL	*786.80 FL
4	1		*REAR BOOT HANDLE	Broken	286.90 FL	*151.60 FL
5	1		*REAR BOOT EMBLEM-VALVE MATIC }	Necessary	63.80 FL	*45.40 FL
6	1		*REAR BOOT EMBLEM-BORNEO MOTOR }	Necessary	45.90 FL	*45.90 FL
7	1		*REAR BOOT W/S GLASS MOULDING	Necessary	529.60 FL	*215.00 FL
8	1		*REAR BOOT INNER TRIM	Broken	389.20 FL	*389.20 FL
9	1		*REAR BUMPER	Broken	981.50 FL	*698.10 FL
10	2		*REAR BUMPER BRACKET L+R	No such part	186.20 FL	*- FL
11	2		*REAR BUMPER RETAINER L+R	Necessary	166.80 FL	*90.00 FL
12	2		*REAR BUMPER REFLECTOR L+R	Broken	184.60 FL	*117.80 FL
13	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
14	2		*TAIL LAMP L+R	N/s Broken/O/s Cut	1,084.20 FL	*823.40 FL
15	2		*REAR FENDER L+R	Dented	1,864.60 FL	*1,843.20 FL
16	2		*REAR FENDER COWLING L+R	Not Damaged	188.40 FL	*- FL
17	10		*REAR FENDER COWLING CLIP L+R	Not Necessary	50.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM L+R	Broken	1,646.80 FL	*960.20 FL
19	10		*REAR FENDER INNER TRIM CLIP L+R	Necessary	50.00 FL	*30.00 FL
20	1		*REAR END PANEL	Dented	785.60 FL	*540.00 FL
21	1		*REAR END PANEL TOP GARNISH	Broken	298.20 FL	*253.00 FL
22	1		*REAR FLOOR PANEL	Dented	984.60 FL	*721.70 FL
23	1		*REAR FLOOR PANEL TOP GARNISH	Not Damaged	463.90 FL	*- FL
24	1		*SPARE TYRE BRACKET	Not Damaged	397.50 FL	*- FL
25	1		*REAR EXHAUST PIPE	Bent	1,181.30 FL	*791.30 FL
26	1		*REAR EXHAUST PIPE GASKET	Necessary	112.90 FL	*89.40 FL
27	2		*REAR REFLECTOR	No such part	116.40 FL	*- FL
28	2		*REAR EXHAUST PIPE MOUNTING	Necessary	136.20 FL	*70.00 FL
29	1		*REAR BOOT W/S GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
30	2		*REVERSE SENSOR	Short Circuit	560.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
32	1		*REAR NUMBER PLATE	Cut	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,383.20	10,524.80
- List Item Discount on L Items 25.00/25.00% (S\$)	3,643.30	2,548.70
Total Parts (S\$)	11,739.90	7,976.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS,TO CUT/WELD,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,400.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	100.00	0.00
4	TO R&R REAR BOOT MECHANISM	New	100.00	80.00
5	TO R&R REAR W/S GLASS	New	140.00	120.00
6	TO R&R UPHOSTERY,GARNISH AND ATTACHMENT PARTS	New	100.00	0.00
7	TO R&R REVERSE SENSOR AND CHECK FUNCTION	New	80.00	60.00
8	TO R&R REAR EXHAUST PIPE SYSTEM	New	100.00	50.00
Gross Labour Cost (\$\$)			3,220.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >