



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 7411R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	BUCKLED	3,980.00	3,980.00
1	BONNET LATCH	TWISTED	668.00	80.70
1	BONNET GRILLE	CRACKED	1,665.00	1,511.50
1	BONNET EMBLEM	NECESSARY	225.00	129.00
1	FRONT BUMPER	DEFORMED	2,995.00	2,732.10
1	FRONT GRILLE PANEL (BACKING)	CRACKED	495.00	243.60
	LESS 10% DISCOUNT		-	-867.69
			10,028.00	7,809.21
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE WITH CASING (SN)	DEFACED	58.00	35.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	50.00	-
			108.00	35.00
	<b><u>LABOUR</u></b>			
	FULLY CHARGE AIRCON GAS.	NOT NECESSARY	90.00	-
	TO REMOVE & CHANGE ALL DAMAGED PARTS. TO KNOCK & REPAIR DAMAGED PARTS & REPAIR FRONT SUPPORT PANEL.		1,120.00	300.00
	TO SPRAY PAINT ALL DAMAGED PARTS.		880.00	500.00
	TO CHECK ALL HEADLAMP WIRING & ALL WIRING.		120.00	30.00
			2,210.00	830.00
	<b>GRAND TOTAL</b>		<b>12,346.00</b>	<b>8,674.21</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,900.00</b>

Report Ref No. CS3/AIG21007574/Gra3q2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.