

PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers Blk 779 Yishun Avenue 2 #01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283 E-mail: admin@priorityservices.sg

Messrs.

Sompo Insurance Pte Ltd

50 Singapore Land Tower

#05-01/06 Raffles Place

Singapore 048623

Bill No

: DN/02161/20

Date

: 31/12/2020

Dr.

To

Survey Fee

(S\$):

250.00

Photographs

(S\$):

Transport

(S\$):

Resurvey

(S\$):

Miscellaneous

(S\$):

Services rendered including photographs and transport charges

(S\$):

250.00

Our Reference

: TP-0175/12/20

Insured

: GBJ 8924 E

Date Of Accident

: 08/10/2020

Policy / Cert. No.

: Paper Survey

Your Claim No

: CMTD2002954/THE

Vehicle

: Nissan NV350 Van (M) - GBG 9907 P

Dollars

: Two Hundred Fifty ONLY

For PRIORITY SERVICES

E & O.E.



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers Blk 779 #01-1545 Yishun Ave 2 Singapore 760779 Tel: 62934822 Fax: 62963283 E-mail: admin@priorityservices.sg

Date:

31 December 2020

Your Ref:

CMTD2002954/THE

Our Ref:

TP-0175/12/20

Motor Claims Department M/s. Sompo Insurance Pte. Ltd. 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623

Attention: Ms. Thelma Choo

Madam,

Inspection of 2017 Nissan NV350 Van (M)

Registration No.: GBG 9907 P Odometer Reading: 81243 km Chassis No.: JN1MC2E26Z0008557

We refer to your instructions to us to conduct a paper survey of the above vehicle. A prerepair survey was conducted on 09-10-2020, followed by inspection of dismantled parts on the same day and resurvey after repairs on 15-10-2020.

The following documents were received: -

- 1) Copy of survey report by M/s. Precise Appraiser Pte Ltd
- 2) 80 copies of photos depicting damages sustained by GBG 9907 P
- 3) Accident reports by drivers of GBG 9907 P and GBJ 8924 E

The vehicle sustained rear damages during an accident on 08-10-2020.

Repair cost submitted was \$13,000.00 lump-sum.

We append below our findings: -

Replacement of Parts		Revised Amount		Our Recommendation		
lpc.	Tail gate	\$	2,195.00	\$	1,816.70	
lpc.	Tail gate logo		98.50		98.50	
lpc.	Tail gate emblem NV350		78.00		64.90	
lpc.	Tail gate emblem URVAN		75.68		64.90	
lpc.	Tail gate outer chrome garnish		449.20		449.20	
lpc.	Tail gate inner lock - refitted		289.90		-	
lpc.	Tail gate lock actuator - no evidence		381.45		_	
	of damage					

1pc. 1pc. 1pc. 1pc. 1pc. 1pc.	Tail gate lock striker – refitted Tail gate weatherstrip – refitted Tail gate inner trim board – refitted Tail gate windscreen Tail gate windscreen moulding Tail gate windscreen wiper arm – refitted	\$	68.10 282.90 204.00 1,309.00 182.25 186.30	\$	891.00 182.25
1pc.	Tail gate windscreen wiper garnish – refitted Rear wing mirror – no evidence of		123.50 332.00		-
•	damage				
lpc.	Rear bumper		641.00		641.00
2pcs.	Rear bumper side retainer - LH		244.20		17.40
4pcs.	Rear bumper lower bracket – LH 2pcs		337.00		100.00
lpc.	Rear bumper step panel		398.10		398.10
lpc.	Rear end panel centre – repaired		581.45		-
2pcs.	Rear end panel side – repaired		575.44		-
lpc.	Rear end panel top garnish – refitted		262.80		-
2pcs.	Tail lamp		962.00		962.00
		\$	10,257.77	\$	5,685.95
	Less 10%	Ψ	1,025.78	Ψ	568.60
	1070		=======		======
		\$	9,231.99	\$	5,117.35
Special	Nett Items:-				
lset	Rear bumper clips	\$	50.00	\$	50.00
lset	Tail gate outer chrome garnish clips	-	30.00	•	30.00
1set	Tail gate inner trim board clips – not necessary		30.00		-
1set	Tail gate windscreen inner seal – not necessary		80.00		-
1set	Tail gate windscreen sealant		60.00		60.00
1set	Tail gate windscreen primer and cleaner – not necessary		50.00		-
lpc.	Sticker 70km/h		30.00		15.00
lpc.	Tail gate sealant		50.00		50.00
1 set	Reverse sensor		300.00		200.00
lpc.	Rear end panel center sealant – not necessary		60.00		-
2pcs.	Rear end panel side sealant – not necessary		120.00		-
lpc.	Rear floor panel sealant – not necessary		80.00		-
lpc.	Rear floor bed top board – refitted		1,600.00		-
lpc.	Tail lamp seal		80.00		50.00
2pcs.	Tail lamp clips LH/RH – not necessary		60.00		-
lpc.	Tail lamp base panel sealant – not necessary		100.00		-
lpc.	Rear number plate – refitted		50.00		
	Total For Parts:-	\$	12,061.99	\$	5,572.35 ======
Labour Charges:-					
To check wiring system.		\$	50.00	\$	50.00

To reprogramme after the accident repair works. – not necessary		120.00	\$ -
To R&R rear windscreen.		150.00	120.00
To transfer tail gate components.		150.00	60.00
To R&R reverse sensor.		80.00	50.00
To R&R rear floor top board.		100.00	25.00
To R&R rear exhaust pipe. – not necessary		150.00	-
Conduct water leak test not necessary		100.00	-
To R&R rear interior tools and equipment. – not necessary		150.00	-
To repair front board, rear end panel, side lamp panels, LH rear fender. To R&R rear bumper, tail lamps, tail gate and other attachments.		1,500.00	750.00
To respray on rear bumper, tail gate, rear end panel, floor board and accident affected areas.		1,500.00	800.00
To carry out body cavity preservation.		150.00	80.00
Total:-	\$	16,261.99	\$ 7,507.35
Lump-sum repairs:	\$	13,000.00	\$ 6,000.00

Estimated period of repairs: 6 working days

Pre-accident Market Value : About \$ 45,000.00 COE rebate : \$ 28,048.00

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES

JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA

Motor Appraiser

Surveyed by:

JEFFREY ONG Motor Appraiser