

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008894/ETCN2**Date:** 29/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00080342100

Claimant Vehicle No : GBK4542U **Insured Vehicle No :** SMP5189T

Date of Loss: 17/08/2021 Nature of Claim: TP Claim No: SNM21D204581/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK4542U**

Make & Model: NISSAN NV200, 1.6 VANETTE DX (A) Engine No: HR16168626D

Reg. Date: 07/08/2020 (Man. Year: 2020) Chassis No: VM20157121

Colour: Silver Odometer: 24829 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,829.30	2,992.20	837.10	21.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,340.00	400.00	22.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,569.30	4,332.20	1,237.10	22.21
+ GST 7.00/7.00% (\$\$)	389.85	303.25	86.60	22.21
Nett Amount (\$\$)	5,959.15	4,635.45	1,323.70	22.21

INSPECTION

Date of Assignment: 24/08/2021

Date Inspected: 30/08/2021 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Apr 2022)	
Parts:	N/A	NISSAN NV200 1.6 VANETTE DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK4542U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,978.00 FN	*1,658.00 FN
2	1		*TAILGATE EMBLEM-NV200	Necessary	95.00 FN	*95.00 FN
3	1		*TAILGATE EMBLEM-VANETTE	Necessary	70.00 FN	*70.00 FN
4	1		*TAILGATE LOCK	Not Necessary	287.00 FN	*- FN
5	1		*TAILGATE INNER HANDLE	Crushed	60.00 FN	*60.00 FN
6	1		*TAILGATE RUBBER	Crushed	98.00 FN	*98.00 FN
7	1		*TAILGATE RH	Broken	277.00 FN	*277.00 FN
8	1		*REAR BUMPER	Cut	486.00 FN	*486.00 FN
9	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	37.00 FN	*- FN
10	10		*REAR BUMPER CLIPS	Necessary	40.00 FN	*30.00 FN
11	1		*END PANEL TOP GARNISH	Cut	85.00 FN	*85.00 FN
12	2		*END PANEL TOP GARNISH CLIPS (BLACK)	Necessary	12.00 FN	*12.00 FN
13	2		*END PANEL TOP GARNISH INSERT (WHITE)	Necessary	12.00 FN	*12.00 FN
14	1		*END PANEL	Repair	165.00 FN	*- FN
15	1		*REAR FENDER RH (NPA)	Repair	0.00 FN	*- FN
16	1		*TAILGATE EMBLEM-NISSAN	Necessary	75.00 FN	*75.00 FN
17	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
18	1		*STICKER-70KM	Necessary	10.00 FS	*10.00 FS
19	1		*STICKER-COMPANY LOGO	Necessary	100.00 FS	*80.00 FS
20	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	4,207.00	3,288.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	377.70	295.80
Total Parts (\$)	3,829.30	2,992.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & TRANSFER REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING	New	80.00	30.00
3	TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION	New	80.00	30.00
4	TO CUT OFF END PANEL.TO REMOVE & REPLACE DAMAGED ITEMS.REALIGN CONNECTION	New	700.00	500.00
5	TO APPLY BODY JOINT SEALANT ON CUTTING AREA	New	80.00	30.00
6	TO RUST PROOF ON REPAIRED AREAS	New	80.00	30.00
7	TO SPRAY PAINT ON REPAIRED AREAS	New	600.00	600.00
Gross Labour Cost (\$)			1,740.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >