

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21008895/GRS3Q2**Date:** 18/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100459533
<b>Claimant Vehicle No :</b>	SHC7764Y	<b>Insured Vehicle No :</b>	SLC8168P
Date of Loss:	23/08/2021	Nature of Claim:	TP
		Claim No:	2892956330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC7764Y</b>		
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Engine No:	G4LEKU388030
Reg. Date:	27/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU183710
Colour:	Yellow	Odometer:	226007 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,375.76	298.40	1,077.36	78.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	910.00	250.00	21.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,535.76</b>	<b>1,208.40</b>	<b>1,327.36</b>	<b>52.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	177.50	84.59	92.91	52.34
<b>Nett Amount (S\$)</b>	<b>2,713.26</b>	<b>1,292.99</b>	<b>1,420.27</b>	<b>52.35</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$125.19/day) (S\$)</b>		250.38		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,645.37</b>		

INSPECTION

Date of Assignment:	23/08/2021	
Date Inspected:	23/08/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	430.90 FL	*- FL
2	1		*FRONT BUMPER UPR BRKT RH	Not Necessary	35.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*FRONT FENDER RH	Repair	588.80 FL	*- FL
5	1		*FRONT FENDER BLUE-DRIVE RH	Necessary	26.60 FL	*26.60 FL
6	1		*FRONT WHEEL CAP RH	Scratched	346.40 FL	*346.40 FL
7	1		*FRT WESTLAKE TYRE RH	Not Necessary	216.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					1,665.70	373.00
- List Item Discount on L Items 20.00/20.00% (S\$)					289.94	74.60
Total Parts (S\$)					1,375.76	298.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	TUFF KOTE	New	40.00	0.00
4	WHEEL ALIGNMENT	New	120.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,160.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >