

REG. NO. BY:

Thavan

REF:

CC3/AIG 21008902/193

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH6238A

Yr Rogn:

24/3/16

Type: M.Car / M.Cycle / Bus / Van / Lorry (Tax) / Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

c.c 1685

Colour:

blue

A/C: Insured / Std / NI / NA

Sp. Reading

593910

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH12B414M64085811

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 705/60 R16

R: 705/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/8/21

D.O.I.

24/8/21/1600

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof/tp or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

rebate: 27630

Date/Time File Pass to?

☐

: Prelim. Report

1/

☐

: Final Report

Date/Time File Return to?

2/

Request Formed:

Listy Sing / E.J. 11

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: WSAI and

Survey Fee:

Transportation:

S + RS \$1

Pmils

Gloss

Total

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 24-Aug-21INSURANCE: AIG ASIA (4S)MODEL: Hyundai i40MVA: LIM T SVEHICLE NO.: SH 6238A

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$1,106.00 ✓ cut
	Rear Bumper Under Cover	1		\$228.00 ✗ r
	Rear Bumper Clips	10	\$2.20	\$22.00 ✓ nec
	SUB TOTAL			\$1,356.00
	LESS 20%			\$271.20
	DISCOUNTED TOTAL			\$1,084.80
	Rear Fender Adv.Sticker RH / LH	2	\$100.00	\$200.00 ✓ nec
	Rear Bumper Adv.Sticker	1		\$50.00 ✓ nec
	Reverse Sensors	1		\$135.70 ✓ cat
	Rear Bumper Mat	1		\$50.00 ✓ nec
	NETT TOTAL			\$435.70
	SPARE PARTS TOTAL			\$1,520.50
	<u>Labour Charge</u>			
	Panel Beating			\$300.00 280
	Spray Painting Charge			\$300.00 250
	R/I Reverse Sensors			\$120.00 50
	TOTAL LABOUR			\$720.00
	ESTIMATE TOTAL			\$2,240.50

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan LHK
 82235769 thuvan@lkh auto.lom
 2 days wp
 1600 24/8/21
 4S after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: