6/14/22, 11:38 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21008903/VGA3Q2

14/06/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082948-01 **Claimant Vehicle**

SHA2842Z Insured Vehicle No: SMK2184C No:

Date of Loss: 24/08/2021 Nature of Claim: ΤP Claim No: 9104288906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA2842Z**

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) G4LEKU405241 Engine No:

Reg. Date: 14/11/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU188838

Colour: Odometer: 195758 km Blue

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 5 mm West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,145.36	378.60	1,766.76	82.35
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,210.00	690.00	520.00	42.98
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	3,355.36	1,068.60	2,286.76	68.15
	+ GST 7.00/7.00% (S\$)	234.88	74.80	160.08	68.15
	Nett Amount (S\$)	3,590.24	1,143.40	2,446.84	68.15
	+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	+ Car Rental (3.0 x S	\$129.47/day) (S\$)	388.41		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,683.81		
	Global Sui	m Settlement (S\$)	1,650.00		

INSPECTION

Date of Assignment: 24/08/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 24/08/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	2		*REAR BUMPER SIDE BRACKET LH/RH	Serviceable	55.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
4	2		*REAR BUMPER STAY LH/RH	Serviceable	276.20 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR BUMPER CENTRE MOULDING	Damaged	451.25 FL	*451.25 FL
7	1		*REAR BUMPER LOWER COVER	Serviceable	155.00 FL	*- FL
8	1		*BUMPER TOW COVER	Serviceable	98.80 FL	*- FL
9	1		*ANTENNA ASSYSMART KEY	Serviceable	40.50 FL	*- FL
10	2		*REAR NUMBER PLATE LAMP	Serviceable	170.60 FL	*- FL
11	1		*REAR BUMPER FOG LAMP	Serviceable	201.10 FL	*- FL
12	1		*REAR BUMPER MAT	Serviceable	50.00 FS	*- FS
13	1		*REAR NUMBER PLATE W/HOLDER	Not Necessary	55.00 FS	*- FS
14	1		*REAR REVERSE SENSOR	Serviceable	180.00 FS	*- FS
==Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,610.45	473.25
			- List Item Discount on	L Items 20.00/20.00% (S\$)	465.09	94.65
				Total Parts (S\$)	2,145.36	378.60
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHECK WIRING AND LIGHTING	New	60.00	30.00
4	TUFF KOTE	New	90.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
		Gross Labour Cost (S\$)	1,210.00	690.00
	Report wa	s unsubmitted during this print-out.		

< END OF ESTIMATES >