



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8326R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL ASSY-FR DR LH	TO REPAIR SEE LABOUR	2,256.40	-
1	MIRROR ASSY-O/S REAR VIEW	TO REPAIR SEE LABOUR	670.00	-
	LESS 20% DISCOUNT		-585.28	-
			2,341.12	-
	<u>NETT ITEMS</u>			
1	FRT DOOR LOGO SONATA CTPL (N)	SCRATCHED	75.00	75.00
1	APP LOGO REAR DOOR L/R CT (N)	SCRATCHED	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF PANEL ASSY-FR DR LH AND MIRROR ASSY-O/S REAR VIEW.		600.00	280.00
	SPRAYPAINT CHARGE.		750.00	500.00
	CHECK ALL LIGHTING.	NOT NECESSARY	50.00	-
	TRANSFER DOOR PART.	NOT NECESSARY	120.00	-
			1,520.00	780.00
	GRAND TOTAL		4,000.62	919.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			750.00

Report Ref No. NS/INC21008904/Gqcn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.