

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC21008904/Gqcn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	13-12-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SFA 6677G	Veh. Ir	spected	SH 8326R	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1141999-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	23/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40 1.7	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	KMHLB41UMHU098188	Colou	r	BLUE	
	Odometer	770122	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	GITI		6 mm	
	L/H Front Tyre	205/60 R16	GITI		6 mm	
	R/H Rear Tyre	205/60 R16	GITI		6 mm	
	L/H Rear Tyre	205/60 R16	GITI		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	22/08/2021	2/08/2021 Inspection Date 23/08/2021			
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					