

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008909/APA3Q2**Date:** 27/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800129170
Claimant Vehicle No :	SJQ8955J	Insured Vehicle No :	SME2603S
Date of Loss:	17/08/2021	Nature of Claim:	TP
		Claim No:	7715221990SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ8955J	Engine No:	R18A1071034
Make & Model:	HONDA CIVIC, 1.8 G (A)	Chassis No:	FD11300993
Reg. Date:	29/05/2009 (Man. Year: 2009)	Odometer:	122849 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,010.88	2,450.24	3,560.64	59.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,160.00	1,970.00	62.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,140.88	3,610.24	5,530.64	60.50
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	9,140.88	2,900.00	6,240.88	68.27
+ GST 7.00/7.00% (S\$)	639.86	203.00	436.86	68.27
Nett Amount (S\$)	9,780.74	3,103.00	6,677.74	68.27
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
(S\$)		3,423.00		
Liabe Amount (80.00%) (S\$)		2,738.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,740.40		
Global Sum Settlement (S\$)		2,750.00		

INSPECTION

Date of Assignment:	23/08/2021	New Hock Teck Motor Pte Ltd (HQ)
Date Inspected:	23/08/2021 Inspected At:	1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	648.30 FL	*648.30 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	56.40 FL	*28.00 FL
3	1		*REAR FENDER RH	Repair	1,452.30 FL	*- FL
4	1		*REAR FENDER INNER SHIELD RH	Torn	158.40 FL	*158.40 FL
5	1		*REAR FENDER AIR VENT RH	Not Necessary	62.50 FL	*- FL
6	1		*REAR FENDER MUDFLAP RH	Not Necessary	52.60 FL	*- FL
7	1		*RH REAR TAILLAMP	Not Necessary	557.40 FL	*- FL
8	1		*RH REAR TAILLAMP LOWER BRACKET	Not Necessary	31.40 FL	*- FL
9	1		*RH REAR LOWER ARM	Bent	654.50 FL	*325.00 FL
10	1		*RH REAR SHOCK ABSORBER	Not Necessary	389.60 FL	*- FL
11	1		*RH REAR UPPER ARM	Not Necessary	342.50 FL	*- FL
12	1		*RH REAR KNUCKLE ARM BEARING	Damaged	215.60 FL	*215.60 FL
13	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	154.60 FL	*- FL
14	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
15	1		*REAR TAILLAMP CLIPS RH	Not Necessary	20.00 FS	*- FS
16	1		*REAR BUMPER LOWER SPOILER	Deformed	850.00 FS	*800.00 FS
17	1		*RH REAR SPORT RIM	Cut	750.00 FS	*480.00 FS
18	1		*RH REAR TYRE	Not Necessary	280.00 FS	*- FS
19	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*REAR BUMPER LOWER SPOILER SEALANT	Necessary	60.00 FS	*40.00 FS
21	1		*REAR BUMPER LOWER SPOILER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,966.10	2,725.30
- List Item Discount on L Items 20.00/20.00% (\$)	955.22	275.06
Total Parts (\$)	6,010.88	2,450.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,200.00	400.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	600.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY RUST PROOF/TUFF COAT ON ACCIDENT AREAS	New	300.00	50.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
6	LABOUR FOR REMOVE & TRANSFER REAR WINDSCREEN GLASS	New	150.00	0.00
7	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY /ROOF LINING	New	250.00	0.00
Gross Labour Cost (\$\$)			3,130.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >