



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 4425H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	CRACKED / BROKEN		
	RIGHT HAND WING MIRROR ASSEMBLY		885.40	885.40
	LESS 10% DISCOUNT		-	-88.54
			885.40	796.86
	<u>LABOUR</u>			
	LABOUR TO DISMANTLE AND RE-FIT WING MIRROR.		150.00	150.00
	SPRAY PAINTING WING MIRROR.		80.00	80.00
			230.00	230.00
GRAND TOTAL			1,115.40	1,026.86

RECOMMENDED COST OF REPAIRS			1,026.86
------------------------------------	--	--	-----------------

Report Ref No. CS/TP21008910/Duce2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.