

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21008911/UPA3Q2

Date:

15/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D18MFL0001888_02

Claimant Vehicle No : FX8596Y**Insured Vehicle No :**

PC7561X

Date of Loss: 08/08/2021

Nature of Claim:

TP

Claim No:

MFL2021D0003423

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FX8596Y**

Make & Model: HONDA CB400, 399cc

Reg. Date: 18/03/2004 (Man. Year: 2004)

Colour: White

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No:

NC23E2061313

Chassis No:

NC391051307

Odometer:

197563 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 R17

Front Left Side: Pirelli 6 mm

Front Right Side: 0 mm

Rear Tyre Size:

160/60 R17

Rear Left Side:

Pirelli 6 mm

Rear Right Side:

0 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,880.80	2,120.20	10,760.60	83.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	530.00	1,350.00	71.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,760.80	2,650.20	12,110.60	82.05
Approved Total (Overridden) (S\$)		2,100.00		

Nett Amount (S\$)	14,760.80	2,100.00	12,660.80	85.77
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		2,250.00		

INSPECTION

Date of Assignment: 24/08/2021

Date Inspected: 24/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2021)	
Parts:	N/A	HONDA CB400 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX8596Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	220.00 FL	*165.00 FL
2	1		*HEADLAMP	Not Necessary	528.00 FL	*- FL
3	1		*HEADLAMP BRACKET	Not Necessary	88.00 FL	*- FL
4	1		*HEADLAMP REAR BRACKET	Not Necessary	105.00 FL	*- FL
5	2		*FORK INNER TUBES	Not Necessary	1,020.00 FL	*- FL
6	2		*FORK OUTER TUBES	Serviceable	1,040.00 FL	*- FL
7	1		*FORK UNDER BRACKET	Not Necessary	385.00 FL	*- FL
8	1		*FORK UPPER BRACKET	Not Necessary	285.00 FL	*- FL
9	1		*FRONT BRAKE DISCS	O/S Bent / N/S Not Necessary	1,120.00 FL	*545.00 FL
10	1		*FRONT RIM SHAFT	Not Necessary	68.00 FL	*- FL
11	1		*FRONT SPORT RIM	Repair	1,100.00 FL	*- FL
12	1		*METER (CASING ONLY)	Cut	1,880.00 FL	*365.00 FL
13	1		*HANDLE -BAR	Not Necessary	580.00 FL	*- FL
14	1		*SET HANDLE -BAR END	Not Necessary	120.00 FL	*- FL
15	1		*SET HAND -GRIP	Not Necessary	110.00 FL	*- FL
16	1		*SIDE MIRRORS	N/S Cut / O/S Not Necessary	220.00 FL	*110.00 FL
17	1		*CLUTCH LEVER	Cut	358.00 FL	*122.00 FL
18	1		*SET FRONT SIGNALS	Not Necessary	480.00 FL	*- FL
19	1		*FUEL TANK	Not Necessary	1,318.00 FL	*- FL
20	1		*FRONT FOOTRESTS	N/S Cut / O/S Not Necessary	150.00 FL	*68.00 FL
21	2		*FRONT FOOTREST BRACKET	Not Necessary	490.00 FL	*- FL
22	1		*GEAR PEDAL	Serviceable	180.00 FL	*- FL
23	1		*REAR FOOTREST	Cut	95.00 FL	*95.00 FL
24	1		*SIDE BOARDS -L/H	Repair	280.00 FL	*- FL
25	1		*SITE STAND	Damaged	110.00 FL	*98.00 FL
26	1		*REAR TAILBOARD	Cracked	380.00 FL	*325.00 FL
27	1		*REAR TAILLAMP	Cracked	480.00 FL	*285.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*SET NUMBER PLATE	Bent	38.00 FS	*10.00 FS
29	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
30	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
31	1		*SET STEERING CONE	Not Necessary	150.00 FS	*- FS
32	1		*SET ENGINE SLIDER	Cut	580.00 FS	*150.00 FS
33	1		*E.R.P IU (LOD)	Not Necessary	155.80 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,199.80	2,338.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,319.00	217.80
Total Parts (\$)	12,880.80	2,120.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE -2TRIPS (LOD)	New	100.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO RESPRAY PAINTING	New	600.00	200.00
4	TO REPAIR BODY FRAME	New	500.00	0.00
5	TO PROVIDE LABOUR	New	600.00	280.00
Gross Labour Cost (S\$)			1,880.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >