

## **LKK Auto Consultants Pte Ltd**

LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 629G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	1,061.30	1,061.30
1	REAR BUMPER BEAM	BENT	537.30	537.30
1	REAR BUMPER REFLECTOR N/S	BROKEN / MISSING	48.50	48.50
2	REAR BUMPER SIDE RETAINERS @\$46.50	NECESSARY	93.00	93.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR	SHORTED	250.00	250.00
1	SET REAR BUMPER LICENCE PLATE LAMP	CRACKED	139.20	139.20
1	REAR LICENCE PLATE W/HOLDER	CRACKED	50.00	50.00
1	REAR END PANEL	BENT	435.70	435.70
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	262.30	-
1	TAILLAMP N/S	NOT NECESSARY	680.20	-
1	BOOTLID	TO REPAIR SEE LABOUR	1,248.30	-
1	BOOTLID REAR LOGO	NECESSARY	66.80	66.80
1	BOOTLID 'MAZDA' EMBLEM	NECESSARY	52.00	52.00
	LESS 20% DISCOUNT		-	-556.76
			4,974.60	2,227.04
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	100.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID.		800.00	700.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	1,000.00
			2,380.00	1,900.00
	GRAND TOTAL		7,354.60	4,127.04

Report Ref No. CS/TP21008912/Uvf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,300.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/TP21008912/Uvf3e2

CHUA KANG SENG

**Licensed Appraiser**