9/28/21, 10:49 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21008913/UUF3N2

112791 km

28/09/2021 Date:

Odometer:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SGG1175C Insured Vehicle No: SMP7091C No:

Date of Loss: 21/08/2021 Nature of Claim: ΤP Claim No: 4635105175SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG1175C

Make & Model: BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A) A1080600N20B20B Engine No: Reg. Date: 16/05/2014 (Man. Year: 2013) Chassis No: WBA5A320X0D334236

Colour: Grey

Engine Capacity: 1997 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 245/457R18 Rear Tyre Size: 245/457R18 Front Left Side: Rear Left Side: Falken 6 mm Falken 6 mm Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,653.81	2,316.16	4,337.65	65.19
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,300.00	830.00	1,470.00	63.91
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,953.81	3,146.16	5,807.65	64.86
	Approved Total (Overridden) (S\$)		2,500.00		
	Nett Amount (S\$)	8,953.81	2,500.00	6,453.81	72.08

INSPECTION

Date of Assignment: 25/08/2021

Imperium Automotive - Kaki Bukit (HQ) Date Inspected: 25/08/2021 Inspected At:

25 Kaki Bukit Road 4, #01-49 Synergy@KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	1,658.00 FN	*- FN
2	1		*REAR BOOT LOGO	Not Necessary	79.00 FN	*- FN
3	1		*REAR BOOT 520 EMBLEM	Not Necessary	89.50 FN	*- FN
4	1		*REAR BUMPER	Dented/Deformed	1,679.85 FN	*1,679.85 FN
5	2		*REAR BUMPER REFLECTOR	Not Necessary	230.00 FN	*- FN
6	1		*REAR BUMPER PDC SENSOR (4 Pcs)	Shorted (2 Pcs only)	1,436.00 FN	*538.00 FN
7	1		*REAR BUMPER UNDERCOVER	Not Necessary	176.50 FN	*- FN
8	1		*REAR BUMPER REINFORCEMENT	Repair	685.00 FN	*- FN
9	2		*REAR BUMPER REINFORCEMENT STAYS	Not Necessary	340.00 FN	*- FN
10	1		*REAR BUMPER INNER FRAME GARNISH	Cracked	289.00 FN	*289.00 FN
11	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	278.00 FN	*- FN
12	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
F=Fra	anchise	part. S=SpcN	Nett. N=NettItemDisc.	-		
				Sub Total (S\$)	7,000.85	2,566.85
	- Nett Item Discount on N Items 5.00/10.00% (S\$)			347.04	250.69	
				Total Parts (S\$)	6,653.81	2,316.16
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	1,000.00	350.00
2	TO RESPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	400.00
3	TO APPLY UNDERCOATING	New	100.00	0.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE, REPLACE DAMAGED LAMP AND CHECK REAR WIRING	New	100.00	30.00
	Gross Labour Cost (S\$)		2,300.00	830.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >