



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 7746E

| Qty                                | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |                      |                           |                   |
| 2                                  | FRONT HEADLAMPS   | DAMAGED              | 4,975.60                  | 4,446.00          |
| 1                                  | FRONT GRILLE  | DAMAGED              | 712.10                    | 382.00            |
| 1                                  | FRONT GRILLE LOGO   | INTACT               | 57.90                     | -                 |
| 1                                  | FRONT GRILLE TOP COVER  | INTACT               | 80.70                     | -                 |
| 1                                  | FRONT BUMPER  | DAMAGED              | 531.10                    | 531.10            |
| 1                                  | FRONT BUMPER INNER SPONGE   | DAMAGED              | 111.80                    | 111.80            |
| 1                                  | FRONT BUMPER FOG LAMP   | INTACT               | 224.60                    | -                 |
| 1                                  | FRONT BUMPER FOG LAMP COVER   | INTACT               | 105.80                    | -                 |
| 1                                  | FRONT BUMPER LOWER GRILLE   | DAMAGED              | 169.60                    | 169.60            |
| 1                                  | FRONT BUMPER REINFORCEMENT  | TO REPAIR SEE LABOUR | 399.50                    | -                 |
|                                    | LESS 25% DISCOUNT   |                      | -1,842.18                 | -1,410.12         |
|                                    |   |                      | 5,526.52                  | 4,230.38          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |                      |                           |                   |
| 1                                  | FRONT NUMBER PLATE C/W FRAME (SN)   | DAMAGED              | 80.00                     | 45.00             |
|                                    |   |                      | 80.00                     | 45.00             |
| <b><u>LABOUR</u></b>               |   |                      |                           |                   |
|                                    | TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.   |                      | 50.00                     | 30.00             |
|                                    | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT. |                      | 900.00                    | 300.00            |
|                                    | TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.                                       |                      | 900.00                    | 300.00            |
|                                    | TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.  |                      | 100.00                    | 30.00             |
|                                    |   |                      | 1,950.00                  | 660.00            |
| <b>GRAND TOTAL</b>                 |   |                      | <b>7,556.52</b>           | <b>4,935.38</b>   |

Report Ref No. CS3/AIG21007145/Eqf3e2-1



|                             |  |  |          |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS |  |  | 4,935.38 |
|-----------------------------|--|--|----------|

Report Ref No. CS3/AIG21007145/Eqf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.