LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008916/VQF3E2

Date: 10/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070052001

Claimant Vehicle SLU3626Y Insured Vehicle No : GBD7466Z

No: SLU3626Y Insured Venicie No: GBD/4662

Date of Loss: 24/08/2021 Nature of Claim: TP Claim No: 2711336068SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU3626Y

 Make & Model:
 TOYOTA PRIUS HYBRID, 1.8 S CVT (A)
 Engine No:
 2ZR8246783

 Reg. Date:
 29/11/2017 (Man. Year: 2017)
 Chassis No:
 ZVW506099221

 Colour:
 Silver
 Odometer:
 309201 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: APLUS 5 mm Rear Left Side: APLUS 5 mm
Front Right Side: APLUS 5 mm Rear Right Side: APLUS 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/08/2021

Apex Motoring

Date Inspected: 25/08/2021 Inspected At: 25 Kaki Bukit Road 4, #01-55 Synergy @ KB

Singapore 417800

Estimated Period of Repair: 8.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$71,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Cut	0.00 F	*-F
2	1	*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
3	1	*REAR END PANEL	Dented	0.00 F	*- F
4	1	*REAR RH TAILLAMP	Cracked	0.00 F	*- F
5	1	*REAR RH FENDER	Dented	0.00 F	*- F
6	1	*REAR RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
7	1	*REAR RH WHEEL RIM	Repair	0.00 F	*- F
8	1	*REAR RH RIM COVER	Cut	0.00 F	*- F
9	1	*REAR RH WHEEL BEARING	Distorted	0.00 F	*- F
10	1	*REAR FENDER 1/4 GLASS SEALANT	Necessary	0.00 F	*- F
11	1	*REAR FENDER AIR GRILLE RH	Cut	0.00 F	*- F
12	1	*REAR RH DOOR	Repair	0.00 F	*- F
13	1	*FRT RH DOOR WIND MIRROR	Repair	0.00 F	*- F
14	1	*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
F=Fra	anchise part.				
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted durir	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >