

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008919/KQCN2**Date:** 15/10/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00124992101	
Claimant Vehicle No :	SMY3746B	Insured Vehicle No :	SLQ3732U	
Date of Loss:	07/08/2021	Nature of Claim:	TP	Claim No: SNM21D204427/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3746B		Engine No:	P520727206
Make & Model:	MAZDA 3, 1.5 (A)		Chassis No:	JM6BP2SAAM1107114
Reg. Date:	03/03/2021 (Man. Year: 2021)		Odometer:	40262 km
Colour:	White			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,035.44	7,852.56	1,182.88	13.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,390.00	510.00	17.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,935.44	10,242.56	1,692.88	14.18
+ GST 7.00/7.00% (S\$)	835.48	716.98	118.50	14.18
Nett Amount (S\$)	12,770.92	10,959.54	1,811.38	14.18

INSPECTION

Date of Assignment:	25/08/2021		
Date Inspected:	25/08/2021	Inspected At:	Comfortdelgro Engineering Pte Ltd (HQ) 205 BRADDELL ROAD Singapore 579701
Estimated Period of Repair:	9.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2021)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY3746B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	997.40 FL	*997.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	541.70 FL	*- FL
3	1		*REAR BUMPER TOW COVER LH	Missing	12.80 FL	*12.80 FL
4	1		*REAR BUMPER REFLECTOR LH	Scratched	36.00 FL	*36.00 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Cracked	33.20 FL	*33.20 FL
6	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*REAR BUMPER SSENSOR OUTER LH	Serviceable	190.00 FL	*- FL
8	1		*TAILLAMP LH	Cracked	538.40 FL	*538.40 FL
9	1		*TAILLAMP SIDE COVER LH	Distorted	14.60 FL	*14.60 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	149.90 FL	*149.90 FL
11	1		*LH REAR FENDER	Bent	1,643.60 FL	*1,643.60 FL
12	1		*LH REAR FENDER INNER SHIELD	Distorted	172.70 FL	*172.70 FL
13	10		*LH REAR FENDER INNER SHIELD CLIPS	Necessary	19.00 FL	*19.00 FL
14	1		*LH REAR FENDER INNER TRIM BOARD	Serviceable	641.90 FL	*- FL
15	1		*LH REAR LOWER ARM (NPA)	No such part	0.00 FL	*- FL
16	1		*LH REAR KNUCKLE ARM (NPA)	Serviceable	0.00 FL	*- FL
17	1		*LH REAR KNUCKLE BEARING WITH HUB	Bent	437.60 FL	*437.60 FL
18	1		*LH REAR SHOCK ABSORBER	Bent	322.20 FL	*322.20 FL
19	1		*LH REAR ABS SENSOR (NPA)	Serviceable	0.00 FL	*- FL
20	1		*LH REAR RIM 16	Dented	890.90 FL	*890.90 FL
21	1		*REAR EXHAUST PIPE	Bent	1,486.80 FL	*1,486.80 FL
22	1		*REAR AXLE	Bent	1,789.30 FL	*1,789.30 FL
23	1		*TAILLAMP PANEL LH	Bent	166.50 FL	*166.50 FL
24	1		*LH REAR FENDER AIR GRILLE	Dented	43.10 FL	*43.10 FL
25	1		*LH REAR FENDER AIR GRILLE PANEL	Dented	107.60 FL	*107.60 FL
26	1		*LH REAR FENDER INNER SHIELD	Cracked	83.50 FL	*83.50 FL
27	1		*REAR BUMPER BRACKET LH	Distorted	33.20 FL	*33.20 FL
28	1		*REAR AXLE LH COVER	Dented	46.70 FL	*46.70 FL
29	1		*FUEL LIP COVER	Dented	440.70 FL	*440.70 FL
30	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
31	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
32	1		*TYRE YOKOHAMA BLUEARTH GT 205/60R16 (70%)	Cut	280.00 FS	*196.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,209.30	9,751.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,173.86	1,899.14
Total Parts (\$\$)	9,035.44	7,852.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
2	TO CUT,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS LH REAR FENDER,LH REAR FENDER INNER PANEL,REAR BUMPER,REAR END PANEL AND ETC	New	1,200.00	1,000.00
3	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS LH REAR FENDER,LH REAR FENDER INNER PANEL,REAR BUMPER,REAR END PANEL AND ETC	New	1,000.00	750.00
4	TO REMOVE AND INSTALL FUEL TANK	New	120.00	80.00
5	TO REMOVE AND INSTALL LH REAR UNDER CARRIAGE	New	240.00	240.00
6	TO REMOVE AND INSTALL REAR SEAL ASSY,LH REAR FENDER INNER TRIM,SPARE TYRE,TYRE BOARD TO FACILITATE REPAIR	New	120.00	120.00
7	TO CONDUCT WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			2,900.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >