



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107896

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/11/2021
Reference CC6/CTI21008922/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBB 1888P
Insured Veh. SJY 6821H
Claim No. SNM21D204679/C02
Policy No. DMPCSNW00045322105
Accident Date 21/08/2021
Inspection Date 24/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21008922/Apa3q2 Date: 17/11/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 6821H	Veh. Inspected	GBB 1888P	
Policy No.	DMPCSNW00045322105	Coverage (\$)	0.00	
Claim No.	SNM21D204679/C02	Excess (\$)	0.00	
Assign From		Assign Date	24/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FB70BBA10556	Colour	WHITE	
Odometer	405248 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	21/08/2021	Inspection Date	24/08/2021	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 1888P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	821.47	821.47
1	LH FRONT BUMPER BRACKET	BENT	119.42	119.42
1	LH FRONT HEADLAMP	CRACKED	635.06	635.06
1	LH FRONT SIGNAL LAMP	CRACKED	227.63	227.63
1	LH FRONT SIDE LAMP	CRACKED	159.75	159.75
1	LH FRONT CORNER PANEL GARNISH	DISTORTED	564.37	564.37
1	LH FRONT DOOR	BUCKLED	2,057.14	1,827.00
2	LH FRONT DOOR HINGE @\$162.54	BENT	325.08	325.08
1	LH FRONT DOOR CHECKER	NOT NECESSARY	83.51	-
1	LH FRONT DOOR WEATHER STRIPE	NOT NECESSARY	424.99	-
1	LH FRONT DOOR LOCK	DAMAGED	389.21	389.21
1	LH FRONT DOOR INNER TRIM BOARD	CRACKED	661.91	661.91
1	LH FRONT DOOR POWER WINDOW MOTOR /GEAR	NOT NECESSARY	1,317.01	-
1	LH FRONT DOOR INNER SEAL	NOT NECESSARY	242.99	-
1	WIPER TANK	DEFORMED	271.98	271.98
1	FRONT PANEL	DENTED	1,580.67	1,422.00
1	FRONT GRILLE	CRACKED	1,190.87	453.00
1	LH FRONT WIPER SIDE GARNISH	CRACKED	53.09	53.09
1	LH FRONT MIRROR ARM	BENT	408.51	235.00
1	LH FRONT MIRROR SQUARE	NOT NECESSARY	101.69	-
1	LH FRONT MIRROR ROUND	NOT NECESSARY	58.78	-
1	LH FRONT DOOR PILLAR	DENTED	1,533.24	1,205.00
1	LH FRONT STEP PANEL	DENTED	503.51	345.00
1	LH FRONT STEP PANEL GARNISH	CUT	320.27	320.27
1	FRONT GRILLE EMBLEM FUSO	NECESSARY	154.96	154.96
1	FRONT PANEL EMBLEM CANTER	NOT NECESSARY	120.98	-
1	FRONT LOGO	NOT NECESSARY	82.54	-
1	FRONT AIR CON COOLING COIL	CRACKED	1,156.08	1,156.08
1	FRONT AIR CON BLOWER MOTOR	CRACKED	3,398.17	1,063.00
	LESS 10% DISCOUNT		-1,896.49	-

Report Ref No. CC6/CTI21008922/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-3,102.57
			17,068.39	9,307.71
	<u>SPECIAL NETT ITEMS</u>			
1	LH FRONT DOOR LTA STICKER (SN)	NECESSARY	40.00	30.00
1	LH FRONT DOOR INNER TRIM BOAED CLIPS (SN)	NECESSARY	60.00	30.00
1	LH FRONT CORNER PANEL GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
			170.00	100.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		1,800.00	1,200.00
	LABOUR FOR SPRAY PAINTING.		1,400.00	900.00
	WIRING CHECK .		80.00	30.00
	LABOUR FOR REMOVE & TRANSFER ALL LH FRONT DOOR FITTING.		300.00	80.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS.		300.00	80.00
	LABOUR FOR REMOVE & REFIT FRONT DASHBOARD TO FACILITATE REPAIR.		300.00	220.00
	LABOUR FOR REMOVE & RENEW AIR COOILING COIL /BLOWSER MOTOR,VACUUM AND TOP UP AIR CON GAS.		300.00	200.00
	LABOUR FOR REMOVE & REFIX FRONT WINDSCREEN GLASS TO FACILITATE THE REPAIR .		150.00	120.00
			4,630.00	2,830.00
	GRAND TOTAL		21,868.39	12,237.71
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,500.00

Report Ref No. CC6/CTI21008922/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 1888P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 1888P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

