

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9336L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	833.50	-
1	FRONT DOOR BLACK TAPE LH	SCRATCHED	25.80	25.80
1	REAR DOOR LH	DENTED / BENT	799.50	799.50
1	REAR DOOR BLACK TAPE LH	NECESSARY / SCRATCHED	25.40	25.40
2	REAR DOOR HINGE LH @\$45.20	NOT NECESSARY	90.40	-
1	REAR DOOR GLASS OUTER MOULDING LH	NOT NECESSARY	42.70	-
1	REAR DOOR REGULATOR LH	NOT NECESSARY	290.40	-
1	REAR DOOR OUTER HANDLE LH	NOT NECESSARY	149.20	-
1	FRONT SIDE MIRROR LH	CRACKED	280.40	280.40
1	FRONT SIDE MIRROR COVER LH	CRACKED	47.30	47.30
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-516.92	-235.68
			2,067.68	942.72
	<u>LABOUR</u>			
	TO TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	180.00	-
	TO TRANSFER REAR DOOR MECHANISM.		180.00	50.00
	TO CHECK WIRING SYSTEM.		120.00	20.00
	TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND REAR FENDER LH.		500.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	680.00
			1,780.00	950.00
GRAND TOTAL			3,847.68	1,892.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/SMR21008925/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.