

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21002352/QES3Q2-1
Date: 01/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLU5643J	Insured Vehicle No :	SLR4458A
Date of Loss:	13/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000712

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5643J		
Make & Model:	MERCEDES-BENZ GLA200, 1.6 AMG LINE (R18 BI) (A)	Engine No:	27091030436236
Reg. Date:	12/09/2014 (Man. Year: 2014)	Chassis No:	WDC1569432J027476
Colour:	White	Odometer:	118972 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,606.10	19,300.50	13,305.60	40.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	2,920.00	1,930.00	39.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,456.10	22,220.50	15,235.60	40.68
Approved Total (Overridden) (S\$)		16,000.00		

Nett Amount (S\$)	37,456.10	16,000.00	21,456.10	57.28
		+ Car Rental (12.0 x S\$100.00/day) (S\$)	1,200.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	17,207.45	

INSPECTION

Date of Assignment: 18/02/2021

Date Inspected: 19/02/2021

Estimated Period of Repair: 8.0 days

Inspected At: PKS Automotive Pte Ltd (HQ)
8 Kaki Bukit Avenue 4 #01 – 52
Singapore 415875

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$66,000

LTA REBATE : \$36,764

NETT VALUE: \$29,236

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2021)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.6 AMG LINE (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU5643J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,898.00 FL	*1,345.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Broken	127.00 FL	*127.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	127.00 FL	*- FL
4	1		*FRONT GRILLE LH	Not Necessary	301.00 FL	*- FL
5	1		*FRONT BUMPER NOZZLE COVER LH	Not Necessary	112.00 FL	*- FL
6	2		*FRONT BUMPER SENSOR LH	Shorted	642.00 FL	*376.00 FL
7	1		*FRONT FENDER LH	Dented	997.00 FL	*997.00 FL
8	1		*FRONT FENDER INNER SHIELD LH	Crumpled	254.00 FL	*254.00 FL
9	1		*FRONT FENDER LOWER GARNISH LH	Crumpled	550.00 FL	*108.00 FL
10	1		*FRONT HEADLAMP LH	Cracked	5,458.00 FL	*2,581.00 FL
11	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	159.00 FL	*- FL
12	1		*FRONT DOOR PANEL LH	Crumpled	1,794.00 FL	*1,794.00 FL
13	2		*FRONT DOOR HINGE LH	Bent	214.00 FL	*214.00 FL
14	1		*FRONT DOOR WEATHERSTRIP LH	Crumpled	374.00 FL	*374.00 FL
15	1		*FRONT DOOR LOCK ASSY LH	Jammed	483.00 FL	*483.00 FL
16	1		*FRONT DOOR BEARING BRACKET LH	Not Necessary	160.00 FL	*- FL
17	1		*FRONT DOOR REGULATOR MOTOR LH	Crumpled	540.00 FL	*540.00 FL
18	1		*FRONT DOOR INNER TRIM LH	Not Necessary	954.00 FL	*- FL
19	1		*FRONT DOOR MIRROR ASSY	Not Necessary	1,154.00 FL	*- FL
20	1		*REAR DOOR PANEL LH	Dented	1,742.00 FL	*1,742.00 FL
21	2		*REAR DOOR HINGE LH	Not Necessary	132.00 FL	*- FL
22	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	374.00 FL	*- FL
23	1		*SILL GARNISH LH	Deformed	1,201.00 FL	*745.00 FL
24	1		*FRONT STEERING RACK AND PINION	Crumpled	5,673.00 FL	*5,430.00 FL
25	1		*STEERING RACK CONTROL UNIT	Not Necessary	1,620.00 FL	*- FL
26	1		*FRONT KNUCKLE ARM LH	Bent	886.00 FL	*886.00 FL
27	1		*FRONT WHEEL HUB AND BEARING LH	Jammed	460.00 FL	*460.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT SHOCK ABSORBER	Bent	772.00 FL	*772.00 FL
29	1		*FRONT LOWER ARM LH (FRONT)	Not Necessary	774.00 FL	*- FL
30	1		*FRONT LOWER ARM LH (REAR)	Not Necessary	696.00 FL	*- FL
31	1		*FRONT UPPER ARM LH	Bent	699.00 FL	*699.00 FL
32	1		*FRONT STABILIZER LINKAGE LH	Not Necessary	168.00 FL	*- FL
33	1		*FRONT LINK ROD LH	Bent	68.00 FL	*68.00 FL
34	1		*FRONT DRIVESHAFT LH	Not Necessary	1,905.00 FL	*- FL
35	1		*TURNING ANGLE PICK SENSOR	Not Necessary	861.00 FL	*- FL
36	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
37	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*30.00 FS
38	1		*SET FRONT DOOR INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
39	1		*RIM	Cracked	1,200.00 FS	*900.00 FS
40	1		*TYRE (70%)	Broken	350.00 FS	*245.00 FS
41	1		*BOT BRAKE FLUID	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,039.00	21,300.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,432.90	1,999.50
Total Parts (\$\$)	32,606.10	19,300.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	REMOVE AND RENEW FRONT SENSOR	New	120.00	30.00
3	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	400.00	100.00
4	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	New	180.00	60.00
5	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS	New	300.00	200.00
6	REMOVE,RENEW STEERING RACK AND PINION	New	250.00	100.00
7	TRANSFER PARTS,ATTACHMENT FROM OLD FRONT DOOR TO NEW	New	200.00	60.00
8	TRANSFER PARTS,ATTACHMENT FROM OLD REAR DOOR TO NEW	New	200.00	0.00
9	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	1,400.00	1,200.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,100.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	40.00
Gross Labour Cost (S\$)			4,850.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >