### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Alfred Toh Date: 26 Aug 2021

## **Preliminary Advice**

Vehicle No : SCA16P **Accident Date** : 23/08/2021

: NISSAN SYLPHY Policy No. Make

DMPCSNW00122142000

Assignment Date : 25/08/2021 Excess : S\$1.300.00

Date of Inspection Est. Duration of Repair : 25/08/2021 : 25

Inspection At : GOLDBELL ENGINEERING PTE LTD (TUAS)

> 10 TUAS AVE 18 SINGAPORE 638894

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,535.12
Revised Amount	:S\$	19,664.85
Check Items (Estimated)	:S\$	7,100.80
Total	:S\$	26,765.65

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 57,000.00 COE / PARF Rebate :S\$ 38,338.00

Salvage Value :S\$

Margin for Repair :S\$ 18,662.00

#### Remarks

- The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: PENDING FOR SOME PARTS PRICES. ( X ) Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.