11/2/21, 11:10 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG21008927/AQCE2

Singapore 079120 Date: 02/11/2021

**REFERENCE** 

Insured/Claimant: WANG GUO LIANG Policy No: 1900094223

Date of Loss: 19/08/2021 Nature of Claim: OD Claim No: 9014395256SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJU9886Y

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC29148

Reg. Date: 30/04/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V5K1027352

Colour: Black Odometer: 41030 km

Engine Capacity: 999 cc
Market Value/New Car Price: \$\$92,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,938.00	6,898.56	6,039.44	46.68
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,002.00	2,542.00	2,460.00	49.18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	17,940.00	9,440.56	8,499.44	47.38
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	17,340.00	8,840.56	8,499.44	49.02
	+ GST 7.00/7.00% (S\$)	1,213.80	618.84	594.96	49.02
	Nett Amount (S\$)	18,553.80	9,459.40	9,094.40	49.02

**INSPECTION** 

Date of Assignment: 25/08/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

24/08/2021 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	39.00 FS	*30.48 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	536.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	297.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	163.00 FS	*-FS
7	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	38.00 FS	*- FS
8	1		*FRONT AIR GUIDE GRILLE - LH	Not Necessary	188.00 FS	*- FS
9	1		*FRONT FENDER - LH	Dented	851.00 FS	*680.40 FS
10	5		*POP RIVET	Necessary	17.00 FS	*13.20 FS
11	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	72.00 FS	*- FS
12	1		*FRONT FENDER BRACKET - LH	Not Necessary	39.00 FS	*- FS
13	1		*FRONT FENDER BRACE - LH	Bent	96.00 FS	*76.48 FS
14	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	169.00 FS	*134.80 FS
15	1		*FRONT HEADLIGHT - LH	Cracked	5,455.00 FS	*4,364.00 FS
16	1		*FRONT HEADLIGHT POWER MODULE - LH	Not Necessary	758.00 FS	*- FS
17	1		*FRONT HEADLIGHT HEAT SINK - LH	Not Necessary	733.00 FS	*- FS
18	1		*FRONT HEADLIGHT CONTROL UNIT	Not Necessary	557.00 FS	*- FS
19	1		*FRONT HEADLIGHT HOSE - LH	Not Necessary	40.00 FS	*- FS
20	1		*FRONT HEADLIGHT LIFT CYLINDER - LH	Not Necessary	142.00 FS	*-FS
21	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
22	1		*WINDSCREEN WASHER RESERVOIR TANK	Not Necessary	206.00 FS	*- FS
23	1		*SUNDRIES	Necessary	300.00 FS	*9.60 FS
F=Fra	nchise	part. S=Spc	Nett.	-		
				Total Parts (S\$)	12,938.00	6,898.56
			Report was unsubmitted during thi	s print-out		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
	Gross Labour Cost (S\$)		5,002.00	2,542.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >