

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008938/AEA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900094576
Claimant Vehicle No :	SNA1343H	Insured Vehicle No :	SML2830R
Date of Loss:	23/08/2021	Nature of Claim:	TP
		Claim No:	7936880881SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA1343H	Engine No:	L15B6026018
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK82105187
Reg. Date:	04/06/2021 (Man. Year: 2020)	Odometer:	3234 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,884.08	1,064.24	7,819.84	88.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	680.00	2,430.00	78.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,994.08	1,744.24	10,249.84	85.46
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	11,994.08	1,300.00	10,694.08	89.16
+ GST 7.00/7.00% (S\$)	839.59	91.00	748.59	89.16
Nett Amount (S\$)	12,833.67	1,391.00	11,442.67	89.16
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
(S\$)		1,691.00		
Liabe Amount (50.00%) (S\$)		845.50		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		881.95		
Global Sum Settlement (S\$)		880.00		

INSPECTION

Date of Assignment:	25/08/2021		
Date Inspected:	02/09/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,267.80 FL	*1,267.80 FL
2	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	386.20 FL	*- FL
3	2		*FRONT DOOR HINGE RH	Not Necessary	99.60 FL	*- FL
4	1		*FRONT DOOR CHECKER RH	Not Necessary	106.40 FL	*- FL
5	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	84.30 FL	*- FL
6	2		*FRONT DOOR GLASS FRAME BLACK STICKER RH	Necessary	158.24 FS	*50.00 FS
7	1		*FRONT DOOR GLASS RH	Not Necessary	468.70 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	89.40 FL	*- FL
9	1		*FRONT DOOR INNER LOCK RH	Not Necessary	297.50 FL	*- FL
10	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Not Necessary	167.40 FL	*- FL
11	1		*FRONT DOOR OUTER STRIP RH	Not Necessary	96.70 FL	*- FL
12	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	20.10 FL	*- FL
13	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	649.80 FL	*- FL
14	1		*FRONT DOOR REGULATOR RH	Not Necessary	353.50 FL	*- FL
15	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	459.60 FL	*- FL
16	1		*FRONT DOOR OUTER KEY LOCK RH	Not Necessary	168.70 FL	*- FL
17	1		*FRONT DOOR SPEAKER RH	Not Necessary	197.60 FL	*- FL
18	2		*FRONT DOOR STOPPER RH	Not Necessary	37.80 FL	*- FL
19	1		*REAR DOOR RH	Repair	986.70 FL	*- FL
20	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	82.40 FL	*- FL
21	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	598.70 FL	*- FL
22	1		*REAR DOOR FRAME WEATHERSTRIP RH	Not Necessary	176.40 FL	*- FL
23	1		*REAR DOOR INNER LOCK RH	Not Necessary	264.70 FL	*- FL
24	1		*REAR DOOR INNER TRIM RH	Not Necessary	765.80 FL	*- FL
25	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	184.80 FL	*- FL
26	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	127.10 FL	*- FL
27	1		*REAR DOOR GLASS SIDE GARNISH RH	Not Necessary	98.70 FL	*- FL
28	2		*REAR DOOR HINGEE RH	Not Necessary	99.60 FL	*- FL
29	1		*REAR DOOR CHECKER RH	Not Necessary	106.40 FL	*- FL
30	1		*REAR DOOR FRONT WEATHERSTRIP RH	Not Necessary	158.60 FL	*- FL
31	1		*REAR DOOR LOCK CATCH RH	Not Necessary	20.10 FL	*- FL
32	1		*REAR DOOR SPEAKER RH	Not Necessary	197.60 FL	*- FL
33	1		*REAR DOOR GLASS REGULATOR GEAR RH	Not Necessary	353.10 FL	*- FL
34	1		*REAR DOOR GLASS RH	Not Necessary	459.30 FL	*- FL
35	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	351.20 FL	*- FL
36	1		*SET FRONT BUMPER CLIP	Not Necessary	80.00 FS	*- FS
37	1		*SET FRONT DOOR TRIM BOARD CLIP	Not Necessary	80.00 FS	*- FS
38	1		*FRONT DOOR GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS
39	1		*SET REAR DOOR INNER TRIM BOARD CLIP	Not Necessary	80.00 FS	*- FS
40	1		*REAR DOOR GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,880.54	1,317.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,996.46	253.56
Total Parts (\$\$)	8,884.08	1,064.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,ADJUST ,KNOCK	New	1,000.00	200.00
2	TO SPRAY PAINT	New	1,000.00	400.00
3	TUFF COAT	New	250.00	0.00
4	WIRING ,BULB CHECKING	New	80.00	0.00
5	TRANSFER FRONT DOOR MECHANISM RH	New	80.00	80.00
6	REMOVE & REFIX FRONT DOOR AUDIO SPEAKER	New	120.00	0.00
7	FOUR WHEEL ALIGNMENT	New	120.00	0.00
8	TRANSFER REAR DOOR MECHANISM	New	80.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			3,110.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >