

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008947/TNCM4**Date:** 18/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00078892104

Claimant Vehicle No : GBK1412G **Insured Vehicle No :** YL4502H

Date of Loss: 12/08/2021 Nature of Claim: TP Claim No: SNM21D204551/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK1412G**

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A) Engine No: YD25056052B

Reg. Date: 29/01/2020 (Man. Year: 2019) Chassis No: JN1MC2E26Z0031480

Colour: Red Odometer: 66847 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/R15 Rear Tyre Size: 195/R15

Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,046.12	641.04	2,405.08	78.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	930.00	1,220.00	56.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,196.12	1,571.04	3,625.08	69.77
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	5,196.12	1,250.00	3,946.12	75.94
+ GST 8.00/8.00% (S\$)	415.69	100.00	315.69	75.94
Nett Amount (S\$)	5,611.81	1,350.00	4,261.81	75.94

INSPECTION

Date of Assignment: 11/05/2022

Date Inspected: 11/05/2022 Inspected At: 37 LOYANG WAY, SINGAPORE 508734
REPAIRER: EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Apr 2023)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK1412G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR FENDER	Repair	2,308.20 FL	*- FL
2	1		*RAILING	Bent	798.60 FL	*545.60 FL
3	1		*JJ EXPRESS STICKER	Necessary	250.00 FS	*150.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					3,356.80	695.60
- List Item Discount on L Items 10.00/10.00% (S\$)					310.68	54.56
Total Parts (S\$)					3,046.12	641.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT, WELD AND PANEL BEAT TO REPLACE AND REPAIR ON DAMAGED PARTS	New	1,200.00	500.00
2	TO PUTTY AND SPRAY PAINT ON LH REAR FENDER AND AFFECTED AREAS	New	800.00	400.00
3	TO APPLY TUFF COAT ON REPAIR AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			2,150.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >