

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008953/AEA3Q2**Date:** 21/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210095364
Claimant Vehicle No :	SKG95J	Insured Vehicle No :	GBL4718A
Date of Loss:	22/08/2021	Nature of Claim:	TP
		Claim No:	6279411216SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG95J	Engine No:	1KRK020751
Make & Model:	TOYOTA RAIZE, 1.0 X CVT (A)	Chassis No:	A200A0020018
Reg. Date:	20/01/2021 (Man. Year: 2020)	Odometer:	7758 km
Colour:	Beige		
Engine Capacity:	996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R16	Rear Tyre Size:	195/65 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,926.00	4,839.75	13,086.25	73.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,720.00	1,680.00	4,040.00	70.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,646.00	6,519.75	17,126.25	72.43
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	23,646.00	5,200.00	18,446.00	78.01
+ GST 7.00/7.00% (S\$)	1,655.22	364.00	1,291.22	78.01
Nett Amount (S\$)	25,301.22	5,564.00	19,737.22	78.01
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,200.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment:	25/08/2021		
Date Inspected:	26/08/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Deformed	1,920.00 FL	*1,250.00 FL
2	1		*REAR BUMPER (LOWER)	Deformed	750.00 FL	*480.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	240.00 FL	*- FL
4	2		*REAR BUMPER SIDE COVER GARNISH	Not Necessary	260.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Not Necessary	192.00 FL	*- FL
6	1		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	130.00 FL	*- FL
7	2		*TAIL LAMP	Not Necessary	1,140.00 FL	*- FL
8	1		*TAIL LAMP LOWER PANEL AIR VENT	Not Necessary	50.00 FL	*- FL
9	2		*REAR FENDER ARCD GARNISH	Not Necessary	380.00 FL	*- FL
10	2		*REAR FENDER INNER TRIM	Not Necessary	1,160.00 FL	*- FL
11	2		*REAR FENDER INNER COWLING	Not Necessary	320.00 FL	*- FL
12	1		*REAR WHEEL HOUSE PANEL LH	Not Necessary	620.00 FL	*- FL
13	1		*TAILGATE	Deformed	2,850.00 FL	*1,850.00 FL
14	2		*TAIL GATE LAMP	Cut	1,060.00 FL	*1,060.00 FL
15	1		*TAIL GATE OUTER GARNISH	Cut	455.00 FL	*455.00 FL
16	1		*TAILGATE LOGO	Necessary	87.00 FL	*87.00 FL
17	1		*TAILGATE EMBLEM RAIZE	Necessary	58.00 FL	*58.00 FL
18	1		*TAILGATE INNER LOCK	Not Necessary	625.00 FL	*- FL
19	1		*TAILGATE INNER LOCK CABLE	Not Necessary	165.00 FL	*- FL
20	1		*TAILGATE WEATHER STRIP	Not Necessary	355.00 FL	*- FL
21	2		*TAILGATE STOPPER	Not Necessary	90.00 FL	*- FL
22	1		*TAILGATE INNER TRIM (LOWER)	Not Necessary	445.00 FL	*- FL
23	1		*TAILGATE WIREHARNES	Not Necessary	680.00 FL	*- FL
24	1		*TAIL GATE WIPER ARM	Not Necessary	210.00 FL	*- FL
25	1		*TAIL GATE WIPER MOTOR	Not Necessary	890.00 FL	*- FL
26	1		*TAIL GATE WIPER ARM BOLT COVER	Not Necessary	48.00 FL	*- FL
27	1		*TAIL GATE WIPER BLADE	Not Necessary	105.00 FL	*- FL
28	1		*TAIL GATE DETECTOR	Damaged	298.00 FL	*298.00 FL
29	1		*TAIL GATE WINDSCREEN GLASS	Not Necessary	1,660.00 FL	*- FL
30	2		*TAIL GATE WINDSCREEN SIDE COVER GARNISH	Not Necessary	320.00 FL	*- FL
31	2		*TAIL GATE DAMPER	Not Necessary	520.00 FL	*- FL
32	1		*REAR END PANEL	Repair	720.00 FL	*- FL
33	2		*REAR END PANEL AIR VENT	Not Necessary	100.00 FL	*- FL
34	1		*REAR END PANEL TOP GARNISH	Deformed	235.00 FL	*235.00 FL
35	1		*REAR END PANEL (OUTER)	Dented	440.00 FL	*440.00 FL
36	1		*REAR STORAGE COVER BOARD	Not Necessary	670.00 FL	*- FL
37	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
38	1		*SET REAR BUMPER (UPPER) CLIP	Necessary	80.00 FS	*30.00 FS
39	1		*SET REAR BUMPER (LOWER) CLIP	Not Necessary	80.00 FS	*- FS
40	1		*SET REAR BUMPER SIDE COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
41	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*- FS
42	1		*SET REAR FENDER ARCD GARNISH CLIP	Not Necessary	80.00 FS	*- FS
43	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
44	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
45	1		*REAR WHEEL HOUSE PANEL SEALANT LH	Not Necessary	150.00 FS	*- FS
46	1		*SET TAIL GATE OUTER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
47	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Not Necessary	80.00 FS	*- FS
48	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
49	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
50	1		*SET TAILGATE WINDSCREEN SIDE COVER GARNISH	Not Necessary	60.00 FS	*- FS
51	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
52	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
53	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
54	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
55	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	22,988.00
					6,393.00	
					- List Item Discount on L Items 25.00/25.00% (\$)	5,062.00
						1,553.25
					Total Parts (\$)	17,926.00
						4,839.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	480.00	40.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	REMOVE AND REPLACE VIDEO RECORDER	New	180.00	50.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
10	TRANFER TAILGATE MECHANISM	New	80.00	80.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
12	TO CHECK DIAGNOSTIC OF VEHICLE MANAGNMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	850.00	0.00
Gross Labour Cost (\$\$)			5,720.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >