

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008954/KVCE2

Date: 04/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00049832100
Claimant Vehicle No: SKN2954E Insured Vehicle No: GBD3358D
Date of Loss: 23/08/2021 Nature of Claim: TP Claim No: SNM21D204730/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN2954E
Make & Model: RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A) Engine No: K9KN837D109240
Reg. Date: 29/05/2014 (Man. Year: 2013) Chassis No: VF1JZ09B348694619
Colour: Metallic Black Odometer: 250753 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,384.05	7,026.95	4,357.10	38.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,510.00	530.00	25.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,424.05	8,536.95	4,887.10	36.41
Approved Total (Overridden) (\$\$)		6,300.00		
(\$\$)	13,424.05	6,300.00	7,124.05	53.07
+ GST 7.00/7.00% (\$\$)	939.68	441.00	498.68	53.07
Nett Amount (\$\$)	14,363.73	6,741.00	7,622.73	53.07

INSPECTION

Date of Assignment: 25/08/2021
Date Inspected: 26/08/2021 Inspected At: Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jul 2022)

Parts: M1-MPV RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKN2954E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	2,760.00 FL	*1,805.00 FL
2	1		*FRONT DOOR STICKER	Necessary	96.00 FL	*96.00 FL
3	9		*FRONT DOOR PROTECTOR CLIPS	Necessary	76.50 FL	*76.50 FL
4	1		*FRONT DOOR PROTECTOR CHROME	Not Necessary	350.00 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE	Dented	360.00 FL	*285.00 FL
6	1		*FRONT DOOR OUTER HANDLE END COVER	Dented	105.00 FL	*105.00 FL
7	1		*FRONT DOOR GLASS	Cut	540.00 FL	*540.00 FL
8	1		*FRONT DOOR GLASS OUTER MOULDING	Scratched	340.00 FL	*180.00 FL
9	1		*FRONT DOOR CHANNEL RUBBER	Not Necessary	247.00 FL	*- FL
10	1		*FRONT DOOR OUTER GARNISH (HORIZONTAL)	Serviceable	250.00 FL	*- FL
11	1		*FRONT DOOR BLACK TAPE	Not Necessary	95.00 FL	*- FL
12	1		*FRONT DOOR INNER INSULATION	Serviceable	280.00 FL	*- FL
13	12		*FRONT DOOR TRIM BOARD CLIPS	Necessary	78.00 FL	*78.00 FL
14	1		*FRONT DOOR WING MIRROR }	Dented / Jammed	720.00 FL	*1,090.00 FL
15	1		*FRONT DOOR WING MIRROR COVER }		245.00 FL	*- FL
16	1		*FRONT DOOR WING MIRROR SIGNAL LAMP }		292.00 FL	*- FL
17	1		*FRONT DOOR WING MIRROR GLASS }		375.00 FL	*- FL
18	1		*FRONT DOOR WING MIRROR GLASS MOTOR }		365.00 FL	*- FL
19	1		*REAR DOOR PROTECTOR CHROME	Serviceable	350.00 FL	*- FL
20	1		*FRONT FENDER LH	Buckled / Cracked	760.00 FL	*760.00 FL
21	1		*HEADLAMP LH	Cut	1,820.00 FL	*1,820.00 FL
22	1		*FRONT BUMPER	Mtg Cracked	1,490.00 FL	*850.00 FL
23	10		*FRONT BUMPER CLIPS	Necessary	100.00 FL	*100.00 FL
24	1		*FRONT BUMPER CORNER RETAINER	Serviceable	310.00 FL	*- FL
25	1		*FRONT DOOR SIDE PROTECTOR	Necessary	40.00 FS	*20.00 FS
26	1		*FRONT DOOR GLASS SOLAR FILM	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,624.50	7,805.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,240.45	778.55
Total Parts (\$\$)	11,384.05	7,026.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK, FOCUS HEADLAMP	New	30.00	20.00
2	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL	New	60.00	30.00
3	LABOUR CHARGE - PANEL BEATING, REPAIRING OF BONNET, FRONT WINDSCREEN PILLAR, FENDER INNER PANEL, DOOR PILLAR AND PART REPLACEMENT	New	700.00	500.00
4	TO RESPRAY AFFECTED AREAS (FRONT BUMPER, FRONT FENDER, FRONT DOOR, REAR DOOR, WING MIRROR)	New	1,100.00	900.00
5	TO DISMANTLE / TRANSFER DOOR FITTINGS / ANCILLARY ACCESSORIES	New	150.00	60.00
Gross Labour Cost (\$\$)			2,040.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >