



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI21008956/Guce2 Date: 13/10/2021 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	GBJ 5276L	Veh. Inspected	SLM 8051P	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM21D203540/C03/GBJ5276L /TAYHP	Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	25/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA STREAM 1.8X	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	RN61089412	Colour	BLACK	
Odometer	387622 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45Z R17	WEST LAKE	6 mm	
L/H Front Tyre	215/45Z R17	WEST LAKE	6 mm	
R/H Rear Tyre	215/45Z R17	WEST LAKE	6 mm	
L/H Rear Tyre	215/45Z R17	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/06/2021	Inspection Date	08/09/2021	
Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	