



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|---|--|------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA | | | Ref: CC4/ASM21008958/Aea3q2 Date: 13/06/2022 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHB 4449H | Veh. Inspected | SKK 7541X |
| | Policy No. | P2419138 | Coverage (\$) | 0.00 |
| | Claim No. | S1M03GEN | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 25/08/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MAZDA 6 | c.c | 1998 |
| | Engine No. | HIDDEN | Year of Reg. | 2013 |
| | Chassis No. | JM6GJ1071D0105327 | Colour | BLACK |
| | Odometer | 209533 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 245/40 R19 | TOYO | 6 mm |
| | L/H Front Tyre | 245/40 R19 | TOYO | 6 mm |
| | R/H Rear Tyre | 245/40 R19 | TOYO | 6 mm |
| | L/H Rear Tyre | 245/40 R19 | TOYO | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 24/08/2021 | Inspection Date | 26/08/2021 |
| | Survey held at | TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 10 Working Days | |