

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008967/TPA3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800096131
Claimant Vehicle No :	GBG8143H	Insured Vehicle No :	SMD3030T
Date of Loss:	25/08/2021	Nature of Claim:	TP
		Claim No:	5682715909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG8143H		
Make & Model:	MERCEDES-BENZ CITAN 109, 1.5 (A)	Engine No:	K9KE628D410494
Reg. Date:	07/11/2017 (Man. Year: 2017)	Chassis No:	WDF4156052U222595
Colour:	Silver	Odometer:	91070 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Gremax 6 mm	Rear Left Side:	Gremax 6 mm
Front Right Side:	Gremax 6 mm	Rear Right Side:	Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,022.69	3,740.10	1,282.59	25.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,280.00	950.00	42.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,252.69	5,020.10	2,232.59	30.78
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	7,252.69	4,000.00	3,252.69	44.85
+ GST 8.00/8.00% (S\$)	580.22	320.00	260.22	44.85
Nett Amount (S\$)	7,832.91	4,320.00	3,512.91	44.85
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,822.00		

INSPECTION

Date of Assignment:	25/08/2021	
Date Inspected:	30/08/2021 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,740.04 FL	*1,740.04 FL
2	1		*FRONT BUMPER RETAINER	N/S Not Necessary /O/SDeformed	146.34 FL	*73.17 FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	299.14 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT TOP GARNISH	Cracked	371.92 FL	*371.92 FL
5	1		*FRONT SUPPORT PANEL	Cracked	742.93 FL	*742.93 FL
6	1		*FRONT FOG LAMP O/S	Not Necessary	135.85 FL	*- FL
7	1		*FRONT FOG LAMP COVER O/S	Not Necessary	98.10 FL	*- FL
8	1		*FRONT FENDER O/S	Repair	407.55 FL	*- FL
9	1		*FRONT FENDER INNER GARNISH O/S	Deformed	599.29 FL	*188.00 FL
10	1		*UNDER ENGINE COVER O/S	Torn	148.15 FL	*148.15 FL
11	1		*FRONT HEADLAMP O/S	Cracked	891.46 FL	*891.46 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,580.77	4,155.67
- List Item Discount on L Items 10.00/10.00% (S\$)	558.08	415.57
Total Parts (S\$)	5,022.69	3,740.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE ,REPAIR & WELD REAR DAMAGED PARTS	New	1,100.00	600.00
2	TO R&R AIR CON SYSTEM TO REFILL & TOP UP AIR CON GAS	New	150.00	100.00
3	TO R&R FRONT RADIATOR	New	120.00	100.00
4	TO R&R LIGHT WIRING	New	60.00	30.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	450.00
Gross Labour Cost (S\$)			2,230.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >