



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 7047J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	YAMAHA FAIRING SET (COLOURED)	CUT	400.00	400.00
1	YAMAHA FAIRING SET (MATTE BLACK)	CUT	180.00	180.00
1	YAMAHA EXHAUST	TO REPAIR SEE LABOUR	420.00	-
1	YAMAHA EXHAUST COVER (BLACK)	NOT NECESSARY	45.00	-
1	YAMAHA EXHAUST COVER (SILVER)	CUT	65.00	65.00
1	YAMAHA EXHAUST GASKET	NOT NECESSARY	15.00	-
1	YAMAHA FOOT STEP BAR	CUT	65.00	45.00
1	YAMAHA RIDER FOOTREST (LEFT)	NOT NECESSARY	25.00	-
1	YAMAHA RIDER FOOTREST (RIGHT)	CUT	25.00	25.00
2	YAMAHA RIDER FOOTREST PIN @\$15.00	NOT NECESSARY	30.00	-
2	YAMAHA RIDER FOOTREST SPRING @\$20.00	NOT NECESSARY	40.00	-
2	YAMAHA PILLION FOOT REST BRACKET @\$65.00	NOT NECESSARY	130.00	-
2	YAMAHA PILLION FOOT REST @\$25.00	NOT NECESSARY	50.00	-
2	YAMAHA PILLION FOOT REST PIN @\$15.00	NOT NECESSARY	30.00	-
1	YAMAHA SIDE STAND	NOT NECESSARY	65.00	-
1	YAMAHA SWINGARM	NOT NECESSARY	380.00	-
1	YAMAHA SWINGARM SHAFT	NOT NECESSARY	50.00	-
2	YAMAHA SWINGARM BUSHING & BEARING @\$25.00	NOT NECESSARY	50.00	-
2	YAMAHA MIRROR SET @\$35.00	NOT NECESSARY	70.00	-
1	YAMAHA REAR SUSPENSION	NOT NECESSARY	280.00	-
1	YAMAHA CLUTCH LEVER	NOT NECESSARY	45.00	-
1	YAMAHA CLUTCH CABLE	NOT NECESSARY	45.00	-
1	YAMAHA CLUTCH LEVER HOLDER	NOT NECESSARY	45.00	-
1	YAMAHA CLUTCH LEVER HOLDER SCREW	NOT NECESSARY	10.00	-
1	YAMAHA CLUTCH CABLE LENGTH ADJUSTER	NOT NECESSARY	20.00	-
1	YAMAHA GEAR SHIFTER	NOT NECESSARY	35.00	-
1	YAMAHA GEAR SHIFTER TIE ROD	NOT NECESSARY	20.00	-
1	YAMAHA GEAR SHIFTER RUBBER	NOT NECESSARY	20.00	-
1	YAMAHA GEAR SHIFTER ARM	NOT NECESSARY	30.00	-
1	NUMBER PLATE REAR	NOT NECESSARY	20.00	-

Report Ref No. CS/AGI21008973/Gqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LIQUIMOLY FRONT BRAKE FLUID	NOT NECESSARY	20.00	-
1	LIQUIMOLY REAR BRAKE FLUID	NOT NECESSARY	20.00	-
1	GIVI BOX RACK	NOT NECESSARY	110.00	-
1	GIVI BOX BASE PLATE	NOT NECESSARY	85.00	-
1	REAR REFLECTOR	NOT NECESSARY	25.00	-
	LESS 10% DISCOUNT		-	-71.50
			2,965.00	643.50
	<u>SPECIAL NETT ITEMS</u>			
1	GIVI BOX 42L (SN)	CUT	210.00	180.00
			210.00	180.00
	<u>LABOUR</u>			
	TOWING 1-TRIP (WORKSHOP TO REPORTING CENTER).	NOT NECESSARY	65.00	-
	TOWING 1-TRIP (REPORTING CENTER TO WORKSHOP).	NOT NECESSARY	65.00	-
	TOWING 1-TRIP (TP COMPOUND TO WORKSHOP).		65.00	50.00
	CHASSIS ALIGNMENT.	NOT NECESSARY	480.00	-
	LABOR.INCLUSIVE OF THE REPAIR OF YAMAHA EXHAUST.		480.00	200.00
			1,155.00	250.00
GRAND TOTAL			4,330.00	1,073.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				850.00

Report Ref No. CS/AGI21008973/Gqf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.