#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008974/AGVF3E2

11/10/2021 Date:

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001800839

**Claimant Vehicle** SLS898J Insured Vehicle No: GX6193C

No:

Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: 261541

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLS898J

Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A) L15B72454975 Engine No:

Reg. Date: 05/10/2017 (Man. Year: 2017) Chassis No: MRHFC1660HT000353

Colour: Odometer: 78158 km Silver

**Engine Capacity:** 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,125.20	2,299.68	3,825.52	62.46
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,580.00	580.00	2,000.00	77.52
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,705.20	2,879.68	5,825.52	66.92
	Approved Total (Overridden) (S\$)		2,300.00		
	Nett Amount (S\$)	8,705.20	2,300.00	6,405.20	73.58

**INSPECTION** 

Date of Assignment: 26/08/2021

Sm Automotive - Kaki Bukit (HQ) Date Inspected: 31/08/2021 Inspected At:

BLOCK C - 1, KAKI BUKIT AVE 6, #01-43

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2021)

Parts: 143 HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS898J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	683.50 FL	*- FL
2	1		*BONNET RUBBER	Not Necessary	31.40 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	116.30 FL	*- FL
4	1		*FRONT GRILLE	Cracked	114.50 FL	*114.50 FL
5	1		*FRONT GRILLE CHROME	Cut	97.80 FL	*97.80 FL
6	1		*FRONT GRILLE BASE	Cracked	185.10 FL	*185.10 FL
7	1		*FRONT GRILLE LOGO	Necessary	17.20 FL	*17.20 FL
8	1		*FRONT BUMPER	Deformed	579.90 FL	*579.90 FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
10	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	43.60 FL	*43.60 FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	79.60 FL	*- FL
12	1		*FRONT BUMPER TOP BEAM	Dented	245.30 FL	*245.30 FL
13	1		*FRONT BUMPER FOG LAMP OUTER GARNISH RH	Not Necessary	260.30 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	1,259.10 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	98.60 FL	*- FL
16	1		*FRONT SUPPORT PANEL SIDE GUIDE GARNISH	Not Necessary	65.30 FL	*- FL
17	1		*FRONT HEADLAMP RH	Cracked	1,357.90 FL	*1,357.90 FL
18	1		*FRONT HEADLAMP TOP GARNISH RH	Cracked	20.80 FL	*20.80 FL
19	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	30.50 FL	*- FL
20	1		*FRONT BUMPER LOWER LIP	Not Necessary	1,200.00 FS	*-FS
21	1		*FRONT GRILLE STICKER	Necessary	160.00 FS	*120.00 FS
22	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
24	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*-FS
25	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*-FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	7,261.50	2,832.10
	- List Item Discount on L Items 20.00/20.00% (S\$)					532.42
				Total Parts (S\$)	6,125.20	2,299.68
			Report was unsubmitted during this prin	nt-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	LABOUR FOR PANEL BEATING	New	1,200.00	350.00		
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	200.00		
3	WIRING CHECK	New	80.00	30.00		
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	New	300.00	0.00		
	Gross Labour Cost (S\$)		2,580.00	580.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >