

ASS. REC. BY:

REF:

TP1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Sta Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____ Yr Regn: _____

Type: Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 740Li c.c.Colour: Ind. Blue A/C: Insured / Std / Nil / NASp. Reading: 6908 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WBA 7T 22040BM 60990Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R20R: 275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 1/1D.O.I. 25/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 For LTA purpose

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :


Lump Sum / I.B.I. (\$



Submit By :	<u>BRYAN TAN</u>
Year Manufacture :	<u>2019</u>
Engine No. :	<u>11245700</u>

Cost / List[illegible]

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



StarAuto
Performance

leading the way

No.176 Sin Ming Drive, #04-05 Autocare, Singapore 575721
Tel: 6452 5515 Fax: 6452 5595

Labour

Vehicle No. : **TBA**
Make & Model : **BMW 740Li M Sport AUTO**

Submit By : **BRYAN TAN**
Year of Manufacture : **2019**

S/No	Labour Description	Estimated	Adjusted Price
1	TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER , REAR BOOT LID, REAR TAIL LAMPS)	\$300.00	✓
2	TO INSTALL FRONT RIGHT HEAD LAMP, TO CHECK WIRING	\$50.00	301
3	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	\$50.00	✓
4	TO RESPRAY ALL REPLACED AND AFFECTED PARTS	\$750.00	✓
		\$1,150.00	
<div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer</p><p>Signature:</p><p>Date:</p></div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.