



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WBA7T22040BM60990

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	USED REAR BOOT LID COVER	BENT	400.00	400.00
1	USED REAR TAIL LAMP RIGHT INNER	CRACKED	350.00	350.00
1	USED REAR TAIL LAMP RIGHT OUTER	BROKEN	300.00	300.00
1	USED REAR BUMPER	BUCKLED / CRACKED	480.00	480.00
			1,530.00	1,530.00
	<u>LABOUR</u>			
	TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, REAR BOOT LID, REAR TAIL LAMPS)		300.00	300.00
	TO INSTALL FRONT RIGHT TAIL LAMP, TO CHECK WIRING.		50.00	30.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		50.00	50.00
	TO RESPRAY ALL REPLACED AND AFFECTED PARTS.		750.00	750.00
			1,150.00	1,130.00
GRAND TOTAL			2,680.00	2,660.00
RECOMMENDED COST OF REPAIRS				2,660.00

Report Ref No. CS/TP21008975/Kvce2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.